AGENDA

THE AITKIN COUNTY PLANNING COMMISSION WILL ASSEMBLE FOR A HEARING ON JANUARY 22, 2024 AT 4:00 P.M. IN THE BOARD ROOM OF THE AITKIN COUNTY GOVERNMENT CENTER (THIRD FLOOR) 307 SECOND STREET NW, AITKIN, MINNESOTA 56431 THE FOLLOWING ITEMS WILL BE REVIEWED:

1. Call the meeting to order.

- 2. Roll call.
- 3. Approve the agenda for the JANUARY 22, 2024 Planning Commission meeting.

4. Election of officers for the 2024 Planning Commission:

- Election of Chairperson
- Election of Vice Chair
- Election of Secretary

OLD BUSINESS: (None)

NEW BUSINESS:

5. Zerek Marsyla/Darin Hill/Ukura's Big Dollar, PO BOX 97, McGregor, MN 55760, Requesting a Conditional Use Permit for the sale of off-sale liquor, in an area zoned Farm Residential. SE NE LESS 4 AC IN DOC 200375, Section Twenty-five (25), Township Forty-eight (48), Range Twenty-four (24), Aitkin County, Minnesota 56431.

APP# 2023-001370

6. Michelle Goltz, 48565 216th PI, McGregor, MN 55760 Requesting an Interim Use Permit to operate a vacation home rental, up to 6 overnight occupants, in an area zoned Shoreland (Big Sandy River). PART LOT 4 IN DOC 422677 (PARCEL B), SECTION NINETEEN (19), TOWNSHIP FORTY-NINE (49), RANGE TWENTY-THREE (23), Aitkin County, Minnesota 56431.

APP# 2023-001347

7. Doua Lor, 176 Hazel St. N, Saint Paul, MN 55119, Requesting an Interim Use Permit to operate a vacation home rental up to 4 overnight occupants, in an area zoned Farm Residential and Shoreland (Section Five Creek). NE NE & THE N 208.14 FT OF THE E 61.34 FT OF THE NW NE, SECTION TEN (10), TOWNSHIP FORTY-SIX (46), RANGE TWENTY-THREE (23), Aitkin County, Minnesota 56431.

APP# 2023-001355

8. Roland Wapola, 107 Lachite Unit 5, Horseshoe Bay, TX 78657, Requesting an Interim Use Permit to operate a vacation home rental up to 6 overnight occupants, in an area zoned Shoreland (Mille Lacs). LOTS 4 & 5 COOLGALE PARK, SECTION THIRTY-THREE (33), TOWNSHIP FORTY-FIVE (45), RANGE TWENTY-SEVEN (27), Aitkin County, Minnesota 56431.

APP# 2023-001353

Aitkin County Planning Commission Agenda Page 2 of 2

9. Gregory & Jessica Malban, 11177 Stillwater Lane, Woodbury, MN 55129, Requesting an Interim Use Permit to operate a vacation home rental up to 5 overnight occupants, in an area zoned Shoreland (Minnewawa). LOT 9 BLK 1 PIERCE ADDITION, SECTION TWENTY-SIX (26), TOWNSHIP FORTY-NINE (49), RANGE TWENTY-THREE (23), Aitkin County, Minnesota 56431. APP# 2023-001354

10. Approval of Minutes, DECEMBER 18, 2023 Planning Commission Meeting.

11. Adjourn.

For more information, contact Planning & Zoning at 218-927-7342 or aitkinpz@co.aitkin.mn.us

AITKIN COUNTY ZONING

NOTICE OF HEARING

THE AITKIN COUNTY PLANNING COMMISSION WILL ASSEMBLE FOR A HEARING ON JANUARY 22, 2024 AT 4:00 P.M. IN THE BOARD ROOM OF THE AITKIN COUNTY GOVERNMENT CENTER (THIRD FLOOR) 307 SECOND STREET NW, AITKIN, MINNESOTA 56431 THE FOLLOWING ITEMS WILL BE REVIEWED:

Zerek Marsyla/Darin Hill/Ukura's Big Dollar, PO BOX 97, McGregor, MN 55760 Requesting a Conditional Use Permit for the sale of off-sale liquor, in an area zoned Farm Residential. SE NE LESS 4 AC IN DOC 200375, Section Twenty-five (25), Township Forty-eight (48), Range Twenty-four (24), Aitkin County, Minnesota.

APPLICATION # 2023-001370

Michelle Goltz, 48565 216th PI, McGregor, MN 55760 Requesting an Interim Use Permit to operate a vacation home rental, up to 6 overnight occupants, in an area zoned Shoreland (Big Sandy River). PART LOT 4 IN DOC 422677 (PARCEL B), SECTION NINETEEN (19), TOWNSHIP FORTY-NINE (49), RANGE TWENTY-THREE (23), Aitkin County, Minnesota.

APPLICATION# 2023-001347

Doua Lor, 176 Hazel St. N, Saint Paul, MN 55119 Requesting an Interim Use Permit to operate a vacation home rental up to 4 overnight occupants, in an area zoned Farm Residential and Shoreland (Section Five Creek). NE NE & THE N 208.14 FT OF THE E 61.34 FT OF THE NW NE, SECTION TEN (10), TOWNSHIP FORTY-SIX (46), RANGE TWENTY-THREE (23), Aitkin County, Minnesota. **APPLICATION # 2023-001355**

Roland Wapola, 107 Lachite Unit 5, Horseshoe Bay, TX 78657 Requesting an Interim Use Permit to operate a vacation home rental up to 6 overnight occupants, in an area zoned Shoreland (Mille Lacs). LOTS 4 & 5 COOLGALE PARK, SECTION THIRTY-THREE (33), TOWNSHIP FORTY-FIVE (45), RANGE TWENTY-SEVEN (27), Aitkin County, Minnesota.

APPLICATION # 2023-001353

Gregory & Jessica Malban, 11177 Stillwater Lane, Woodbury, MN 55129 Requesting an Interim Use Permit to operate a vacation home rental up to 5 overnight occupants, in an area zoned Shoreland (Minnewawa). LOT 9 BLK 1 PIERCE ADDITION, SECTION TWENTY-SIX (26), TOWNSHIP FORTY-NINE (49), RANGE TWENTY-THREE (23), Aitkin County, Minnesota. APPLICATION # 2023-001354

AITKIN COUNTY ZONING



Conditional Use *(not specified below) App. # App-2023-001370, UID # 209466 App. Status: Pending Review

> Meeting Date: 1/22/24 Date complete: 12/26/23 60 Day: 2/23/24

Contact Information

Aitkin County Planning & Zoning / Environmental Services 307 2nd Street NW, Room 219 Aitkin, MN 56431 Phone: 218-927-7342 Fax: 218-927-4372 Email: aitkinpz@co.aitkin.mn.us

Are you the property owner?	Yes
If we have questions on the application who should we contact?	Name: Zerek Marsyla/Darin Hill Phone: (218) 513 - 3731 Email Address: zmarsyla@frontier.com Mailing Address: PO BOX 97 McGregor MN 55760

12/26/23, 11:47 AM

OneGov

Project Location

Property:	Property Location		Legal Description		Property Attributes		Owner Information	Tax Payer Information		
	Parcel Number	Property Address	Township or City Name	Legal Description	Plat Name	Section- Township- Range	Lake Class	Lake Name	Owner Name(s)	Taxpayer Name(s)
	14-0- 041802	41561 STATE HWY 65 MCGREGOR, MN 55760	JEVNE TWP	SE NE LESS 4 AC IN DOC 200375		S:25 T:48 R:24			UKURA'S BIG DOLLAR	UKURA'S BIG DOLLAR
Driving directions to the property from Aitkin:	North on Hw	vy 65, on left side.								

Brief Narrative

Brief Narrative:	Requesting a CUP for off-sale liquor in new building built in 2021. Our existing conditional use permit for grocery/supermarket does not cover off-sale.
Please give a detailed explanation on why and how this proposal is meeting the Comprehensive Land Use Plan:	This land use meets the goals of the comprehensive land use for the county by promoting commercial business development and job creation.
How will this proposal be compatible with existing land uses?	This proposal for off-sale liquor is compatible with the existing land use for the grocery store and is compatible with many businesses in the general area (hotel, community center, restaurant, Savanna Properties wood processing to name a few).
Is this proposal meeting the Findings of Fact?	Yes

12/26/23, 11:47 AM

Detailed Operational Plan

Detailed Operational Plan:	New 50x100 building for off-sale liquor next to existing grocery store. The current days/hours of operation for off-sale are: M-T 9-7:30 F 9-8 Sat 9-7:30 Sun 11-3
----------------------------	---

A Scaled Drawing

Septic Compliance

Is there an existing septic system on	Ves
the property?	

Property Deed

Please attach the property deed(s):	
	File 1: 🖶 457773-p0001p0004.pdf
	File 2: 🖶 468303-p0001p0004.pdf
	L

Other

Other Information (if necessary):	A compliance inspection on the septic will be submitted to Planning & Zoning prior to the meeting.	
-----------------------------------	--	--

Terms

Conditional Use Terms & Conditions

The landowner or authorized agent hereby certifies that to the best of their knowledge the application and supporting documents are a factual representation of the proposed project. The landowner or authorized agent agrees that, in making application, the landowner grants permission to Aitkin County, at reasonable times, to enter the property to determine compliance of the application with applicable Local, County or State Ordinances or Statutes. It is the applicant's responsibility to contact other Local, County or State agencies to ensure the applicant has complied with all relevant Local, County or State Ordinances or Statutes.

Submittal of the above materials does not always constitute a complete application. Other information may be necessary to complete the application based on the type of request and onsite inspection.

The landowner or authorized agent may make application for a Conditional Use permit agreeing to do such work in accordance with all Aitkin County Ordinances. The landowner or authorized agent agrees that the application, site plan, and all other attachments submitted herewith are true and accurate and shall become a part of the permit. The landowner or authorized agent agrees that, in making application for a Conditional Use permit, the landowner grants permission to Aitkin County, at reasonable times, to enter the property to determine compliance of the application with applicable Local, County or State Ordinances or Statutes. It is the applicants sole responsibility to contact other Local, County or State Ordinances or Statutes.

All corners of the proposed structure(s) need to be staked with visible flags, ribbon, or lathes prior to onsite inspection by Aitkin County.

Conditional Use Permit fees are non-refundable if denied or approved.

I acknowledge that by submitting this application, the application and its attachments are public information.

Invoice #59133 (12/18/2023) Expected Payment Method: Unknown

Charge	Cost	Quantity	Total
Conditional Use Application Fee added 12/18/2023 8:28 AM \$650 Flat Fee	\$650.00	x 1	\$650.00
Recording Fee added 12/18/2023 8:28 AM \$46 Flat Fee	\$46.00	x 1	\$46.00
Grand Total			
Total		\$696.00	
Payment 12/18/2023		\$696.00	
		Due	\$0.00

Approvals

OneGov

Approval	Signature
Applicant	Zerek Marsyla/Darin Hill - 12/26/2023 11:02 AM - witnessed by Shannon Wiebusch
	515f2e266e848eed3cd77bc45cedfe89
	7a64808d238add28b7327a82b652ce25
#1 Admin	Shannon Wiebusch - 12/26/2023 11:13 AM
	7d8f67c4f4c49fcc259984e745e369d1
	a79866cb3410cb021db2b9255e588b6b
#2 Planning Commission	

Public Notes

Text:	To be heard at January 22, 2023 PC Meeting. CI on septic to be submitted prior to the meeting.	
File(s):	()	

Admin Staff


Date the application was complete:	12/26/2023
This review has been started by:	Shannon Wiebusch 🗸
Zoning District of project location:	Farm Residential 🗸
Project located in the floodplain?	No 🗸
Is the parcel a Lot of Record before 1-21-92 or have alternate sites been identified?	Yes 🗸

12/26/23, 11:47 AM

an after-the-fact application?

OneGov

Print View



CRV Not Required No Delinquent Taxes and Transfer Entered Kirk Peysar, County Auditor

Doc No: A457773

PRO 3/4

\$46.00

REC FEE

Certified Filed and/or Recorded on 7/7/2020 10:16 AM

Office of the County Recorder Aitkin County, Minnesota Michael T. Moriarty, County Recorder

Package: 66955 Liz

This cover sheet was added by the Aitkin County Recorder's Office to allow space for the recording information of this document. It is not intended to alter the document/certified copy.

This cover sheet is now a permanent part of the recorded document.

(Top 3 inches reserved for recording data)						
DEED OF DISTRIBUT by Individual Persona		Minnesota Uniform Conveyancing Blanks Form 10.5.1 (2016)				
NO DEED TAX DUE		DATE: June 25, 2020 (month/day/year)				
Ashley	Carlstrom					
		(insert name of each Personal Representative)				
as Personal Represent	ative of the Estate ofMark	Kenneth Ukura				
("Grantor"), hereby cor	nveys and quitclaims to _ Uku	, Decedent , single ■ married □ at the time of death (check applicable box), (if "married" is checked, then attach a Consent of Spouse [Form 70.1.1]) ura's Big Dollar, LLC, a Limited Liability Company under the laws of the State of				
Minnesota	,	(insert name of each Grantee)				
Milliesota	🗖 tenente in common	("Grantee"), as				
(Check only one box.)	 tenants in common, joint tenants, 	(If more than one Grantee is named above and either no box is checked or both boxes are checked, this conveyance is made to the named Grantees as tenants in common.)				
real property in <u>Aitkin</u> See Attached Exhibi		County, Minnesota, legally described as follows:				

Check here if all or part of the described real property is Registered (Torrens)

together with all hereditaments and appurtenances belonging thereto.

and Na

Granto ()Ву ley Čaristrom

By: (signature of Personal Representative)

Note: This deed should be used only for distribution.

Minnesota Uniform Conveyancing Blanks Form 10.5.1

State of Minnesota, County of _____ Aitkin Tune 2 2020 by Ashley Carlstrom This instrument was acknowledged before me on (month/day/year) (insert name of each Personal Representative) as Personal Representative of the Estate of Mark Kenneth Ukura Decedent. (Stamp) (signature of notarial of Shari S Larson ary Public SHARI S. LARSON Title (and Rank): NOTARY PUBLIC - MINNESOTA Wy Commission Expires Jan. 31, 202 25 My commission expires: (month/day/year)

THIS INSTRUMENT WAS DRAFTED BY: (insert name and address)

Shari S. Larson, Atty. ID#0187689 LARSON LAW OFFICE P. O. Box 456 McGregor, MN 55760 218-768-4005 larsonlwshari@gmail.com TAX STATEMENTS FOR THE REAL PROPERTY DESCRIBED IN THIS INSTRUMENT SHOULD BE SENT TO: (insert legal name and residential or business address of Grantee) Ukura's Big Dollar 41561 State Hwy. #65 P. O. Box 97 McGregor, MN 55760

Page 2 of 2

450

EXHIBIT A

· · · ·

Southeast Quarter of Northeast Quarter (SE ¼ of NE ¼) of Section Twenty-five (25), Township Forty-eight (48), Range Twenty-four (24), subject to highway easements and mineral reservation of record; subject to the following exceptions: Except any liens or incumbrances created or suffered to be created by the acts or defaults of the grantees.

LESS: That part of the Southeast Quarter of Northeast Quarter (SE ¼ of NE ¼) of Section Twenty-five (25), Township Forty-eight (48), Range Twenty-four (24), described as follows:

Commencing at the East Quarter corner of said Section 25; thence on an assumed bearing of North along the East line of said Southeast Quarter of Northeast Quarter (SE $\frac{1}{4}$ of NE $\frac{1}{4}$) a distance of 572.58 feet; thence West a distance of 100.00 feet to the westerly right of way line of Minnesota Trunk Highway No. 65 and the actual point of beginning of the tract to be described; thence continuing West a distance of 286.00 feet; thence South a distance of 104.00 feet; thence East a distance of 286.00 feet to the westerly right of way line of Minnesota Trunk Highway No. 65; thence North along said right of way line a distance of 104.00 feet to the actual point of beginning. Subject to restrictions, reservations and easements of record, if any.

AND LESS: That part of the Southeast Quarter of Northeast Quarter (SE ¼ of NE ¼) of Section Twenty-five (25), Township Forty-eight (48), Range Twenty-four (24), described as follows: Commencing at the East Quarter corner of said Section 25; thence on an assumed bearing of North along the East line of said Southeast Quarter of Northeast Quarter (SE ¼ of NE ¼) of Section 25 a distance of 682.21 feet to a point hereby designated as Point A; thence North 87 degrees 58 minutes West a distance of 119.55 feet; thence North 61 degrees 52 minutes West a distance of 173.64 feet; thence North 89 degrees 24 minutes West a distance of 282.95 feet; thence South 01 degrees 28 minutes East a distance of 115.53 feet to the actual point of beginning of the tract to be described; thence South 81 degrees 36 minutes West a distance of 775.0 feet; thence North 01 degrees 28 minutes West a distance of 225.0 feet; thence North 81 degrees 36 minutes East a distance of 775.0 feet; thence South 01 degrees 36 minutes East a distance of 775.0 feet; thence South 01 degrees 36 minutes East a distance of 775.0 feet; thence South 01 degrees 36 minutes East a distance of 775.0 feet; thence South 01 degrees 36 minutes East a distance of 775.0 feet; thence South 01 degrees 36 minutes East a distance of 775.0 feet; thence South 01 degrees 36 minutes

Together with an easement for the purpose of ingress to and egress from the aforedescribed tract to Minnesota Trunk Highway No. 65. Said easement being 33.0 feet in width and being 16.5 feet on each side of the following described line: Beginning at the afore-designated Point A; thence North 87 degrees 58 minutes West a distance of 119.55 feet; thence North 61 degrees 52 minutes West a distance of 173.64 feet; thence North 89 degrees 24 minutes West a distance of 300.00 feet and there terminating. Subject to Aitkin County zoning ordinances and other restrictions, reservations and easements of record, if any. Transfer Entered Kirk Peysar, County Auditor

Doc No: A468303

JUD 1/1

\$46.00

REC FEE

Certified Filed and/or Recorded on 12/7/2021 9:00 AM

Office of the County Recorder Aitkin County, Minnesota Michael T. Moriarty, County Recorder

Package: 75333 Liz

This cover sheet was added by the Aitkin County Recorder's Office to allow space for the recording information of this document. It is not intended to alter the document/certified copy.

This cover sheet is now a permanent part of the recorded document.

Filed in District Court State of Minnesota

Tinaners, Karen Nov 24 2021 1:15 PM

COUNTY OF AITKIN

STATE OF MINNESOTA

NINTH JUDICIAL DISTRICT CIVIL DIVISION Case Type: Other Civil (Quiet Title)

Ukura's Big Dollar, LLC, a limited liability company under the laws of Minnesota,

Plaintiff,

VS.

Mark K. Ukura a/k/a Mark Kenneth Ukura, Estate of Mark K. Ukura a/k/a Mark Kenneth Ukura, Linda D. Ukura a/k/a Linda Diane Ukura, Estate of Linda D. Ukura a/k/a Linda Diane Ukura, and all the unknown heirs of the above named who are deceased and all other persons unknown claiming any right, title, estate, interest or lien in the real estate described in the Complaint herein,

Defendants.

The above entitled action came on for hearing before the Honorable David F. Hermerding, Judge of District Court of Aitkin County, on the 24th day of November, 2021, at 10:45 a.m., at the Aitkin County Courthouse in the City of Aitkin, Minnesota. The Plaintiff appeared by and through counsel, Heinrich A. Brucker of Ryan, Brucker & Kalis, Ltd., Aitkin, Minnesota. No appearances were made by any of the Defendants.

Now, therefore, upon the evidence presented by and on behalf of the Plaintiff, and upon all of the evidence adduced at said hearing and upon all of the files and records herein, the Court makes the following:

Court File No. 01-CV-21-589

FINDINGS OF FACT, CONCLUSIONS OF LAW AND ORDER FOR JUDGMENT

DISTRICT COURT

FINDINGS OF FACT

I.

That Plaintiff, Ukura's Big Dollar, LLC, a limited liability company under the laws of

Minnesota, is the owner in fee of the following described real property located in Aitkin County,

Minnesota:

That part of the Southeast Quarter of Northeast Quarter (SE¼ of NE¼) of Section Twenty-five (25), Township Forty-eight (48), Range Twenty-four (24), described as follows: Commencing at the East Quarter corner of said Section 25; thence on an assumed bearing of North along the East line of said Southeast Quarter of Northeast Quarter (SE¼ of NE¼) a distance of 572.58 feet; thence West a distance of 100.00 feet to the westerly right of way line of Minnesota Trunk Highway No. 65 and the actual point of beginning of the tract to be described; thence continuing West a distance of 286.00 feet; thence South a distance of 104.00 feet; thence East a distance of 286.00 feet to the westerly right of Minnesota Trunk Highway No. 65; thence North along said right of way line a distance of 104.00 feet to the actual point of beginning.

Aitkin County, Minnesota (Abstract)

П.

That Plaintiff, Ukura's Big Dollar, LLC, a limited liability company under the laws of

Minnesota, is in actual possession of the real property legally described in Paragraph I above.

III.

That all of the Defendants have been properly served and are in default.

IV.

That the Defendants have no claim, estate, lien or interest in the above described real property.

And from the foregoing Findings of Fact, the Court makes the following:

CONCLUSIONS OF LAW

1. Plaintiff, Ukura's Big Dollar, LLC, a limited liability company under the laws of

Minnesota, is the owner in fee of that certain real property located in Aitkin County, Minnesota,

and legally described as follows:

That part of the Southeast Quarter of Northeast Quarter (SE¼ of NE¼) of Section Twenty-five (25), Township Forty-eight (48), Range Twenty-four (24), described as follows: Commencing at the East Quarter corner of said Section 25; thence on an assumed bearing of North along the East line of said Southeast Quarter of Northeast Quarter (SE¼ of NE¼) a distance of 572.58 feet; thence West a distance of 100.00 feet to the westerly right of way line of Minnesota Trunk Highway No. 65 and the actual point of beginning of the tract to be described; thence continuing West a distance of 286.00 feet; thence South a distance of 104.00 feet; thence East a distance of 286.00 feet to the westerly right of Minnesota Trunk Highway No. 65; thence North along said right of way line a distance of 104.00 feet to the actual point of beginning.

Aitkin County, Minnesota (Abstract)

2. Defendants have no claim, estate, lien or interest in the above-described real property.

LET JUDGMENT BE ENTERED ACCORDINGLY.

STATE OF MINNESOTA COUNTY OF CROW WING SS I, D. Anderson Count Administrator in and for said County and State, do hereby county that the foregoing is a full and true copy of the original remaining of the and or record in my office. Dated the day of Court Administrator Crow Wing County Denistr

Dated: <u>November 24</u>, 2021

Hermerding, David Nov 24 2021 10:50 AM David F. Hermerding District Court Judge

I hereby certify that the foregoing Order constitutes the Judgment of this Court Court Administrator: Paula Lang

Nacey, Lois Nov 29 2021 8:59 AM 3



EXPERT SERVICE. LASTING VALUE. CLEAN WATER

Septic System Compliance Inspection – Existing System

DATE 12/27/2023

Property Owner: Ukura's Big Dollar Store Street Address: 41561 Minnesota 65 City, State, Zip: McGregor, MN 55760

Dear: Cory Marsyla and Aitkin County,

A compliance inspection was performed at the above location. Soil investigations were conducted to determine the seasonal high water table, the drain field was also inspected to ensure there was no ponding or leakage, and the septic tank was inspected. The system was found to be $\underline{.}$

- <u>Impact on Public Health:</u> Compliant; no impact on public health.
- <u>Tank Integrity:</u> Compliant; tank(s) are functioning at operating level and are protecting the groundwater.
- <u>Other Compliance Conditions:</u> Compliant; meets conditions of A, B, & C.
- <u>Soil Seperation:</u> Compliant, soil has 3' of vertical separation to saturated soils.
- <u>Operating Permit and Nitrogen BMP:</u> Operating permit requirements have been met.

I included a copy of the compliance documents and site sketch. Copies were sent to Aitkin County on your behalf. If you have any further questions, please do not hesitate to give us a call. Thank you for your business!

Sincerely,

Eric Otte, Lic. No. 2624 Advanced Design and Compliance- C8453 Office: 320-983-2447 ericotte@septiccheck.com



EXPERT SERVICE. LASTING VALUE. CLEAN WATER

Disclaimer

The septic system inspection conducted for this property, meets the MN chapter 7082.0700 Subp. 4. Requirements for existing system inspections.

We recommend this system be serviced and inspected at least every 36 months by a septic professional.

Water use in excess of 50% of the design flow of the septic system may lead to premature failure.

This inspection does not guarantee future performance.

Additions to the home or use of the property may require the property owner to increase the system capacity.



520 Lafayette Road North St. Paul, MN 55155-4194

Compliance inspection report form

Existing Subsurface Sewage Treatment System (SSTS)

Logal tracking number

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf.

Property information

Parcel ID# or Sec/Twp/Range: _14-0-041802	Reason for Inspection	Property Transfer	
Local regulatory authority info: Aitkin County			
Property address: 41561 Minnesota 65 McGregor, MN 55760			
Owner/representative: Cory Marsyla		Owner's phone: 218-670-0430	
Brief system description: 2-1960 gallon septic tanks, then a 1960 1200 GPD mound.	with a VBT treatment unit,	and a 1960 duplex pump tank and a	

System status

System status on date (mm/dd/yyyy): 12/27/2023

Compliant – Certificate of compliance*

(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)

*Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.

□ Noncompliant – Notice of noncompliance

Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.

An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.

Reason(s) for noncompliance (check all applicable)

Impact on public health (Compliance component #1) – Imminent threat to public health and safety

Tank integrity (Compliance component #2) - Failing to protect groundwater

Other Compliance Conditions (Compliance component #3) - Imminent threat to public health and safety

Other Compliance Conditions (Compliance component #3) – Failing to protect groundwater

System not abandoned according to Minn. R. 7080.2500 (Compliance component #3) – Failing to protect groundwater

Soil separation (Compliance component #5) – *Failing to protect groundwater*

Operating permit/monitoring plan requirements (Compliance component #4) – Noncompliant - local ordinance applies

Comments or recommendations

Certification

I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage.

By typing my name below, I certify the above statements to be true and correct, to the best of my knowledge, and that this information can be used for the purpose of processing this form.

Business name: Sep	tic Check	1- M	Certification number: C8453
Inspector signature:	Eric Otte	4m otto	License number: 2624
	(This do	cument has been electronically signed)	Phone: 320-983-2447

Necessary or locally required supporting documentation (must be attached)

Soil observation logs	🛛 System/As-Built	Locally required forms	🛛 Tank Integrity Assessment	Operating Permit
\Box Other information (list):				

Page 2 of 5

1. Impact on public health – Compliance component #1 of 5

Compliance criteria:		Attached supporting documentation:	
System discharges sewage to the ground surface	🗌 Yes* 🛛 No	☐ Other: ☐ Not applicable	
System discharges sewage to drain tile or surface waters.	🗌 Yes* 🛛 No		
System causes sewage backup into dwelling or establishment.	🗌 Yes* 🛛 No		
Any "yes" answer above indicates imminent threat to public health an	•	_	

Describe verification methods and results:

Visual Inspection

2. Tank integrity – Compliance component #2 of 5

Compliance criteria:		Attached supporting documentation	on:			
System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ⊠ No	☑ Empty tank(s) viewed by inspector Name of maintenance business:	Kangas			
Sewage tank(s) leak below their	🗌 Yes* 🛛 No	License number of maintenance business: L2526				
designed operating depth?		Date of maintenance:	12/27/2023			
		Existing tank integrity assessment (A	ttach)			
If yes, which sewage tank(s) leaks:		Date of maintenance (mm/dd/yyyy): (must be wi	thin three years)			
Any "yes" answer above indic is failing to protect groundwat	-	(See form instructions to ensure asse Minn. R. 7082.0700 subp. 4 B (1))	ssment complies with			
		Tank is Noncompliant (pumping not needed)	cessary – explain below)			
		Other:				
Describe verification methods and	l results:					

Pumped, cleaned and visually inspected, no issues seen.

3. Other compliance conditions – Compliance component #3 of 5

	 3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or uns □ Yes* ☑ No □ Unknown 	ecured?
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safe	ty? 🗌 Yes* 🛛 No 🗌 Unknown
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.	
	3c. System is non-protective of ground water for other conditions as determined by inspector?	🗌 Yes* 🛛 No
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	🗌 Yes* 🛛 No
	*Yes to 3c or 3d - System is failing to protect groundwater.	
	Describe verification methods and results:	
	Attached supporting documentation:	
	Attached supporting documentation: Not applicable	
4.	Attached supporting documentation: Not applicable Operating permit and nitrogen BMP* – Compliance component #4 of	of 5 🗌 Not applicable
<u>4.</u>	Operating permit and nitrogen BMP* – Compliance component #4 of	of 5
<u>4.</u>	Operating permit and nitrogen BMP* – Compliance component #4 of	If "yes", A below is required
<u>4.</u>	Operating permit and nitrogen BMP* – Compliance component #4 of Is the system operated under an Operating Permit? ☑ Yes □ No	If "yes", A below is required
<u>4.</u>	Operating permit and nitrogen BMP* – Compliance component #4 of Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes ⊠ No	If "yes", A below is required If "yes", B below is required
<u>4.</u>	Operating permit and nitrogen BMP* – Compliance component #4 of Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes ⊠ No BMP = Best Management Practice(s) specified in the system design	If "yes", A below is required If "yes", B below is required
<u>4.</u>	Operating permit and nitrogen BMP* – Compliance component #4 of Is the system operated under an Operating Permit? □ Yes □ No Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be complete	If "yes", A below is required If "yes", B below is required
<u>4.</u>	Operating permit and nitrogen BMP* – Compliance component #4 of Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? Is the system required to employ a Nitrogen BMP specified in the system design? Is the answer to both questions is "no", this section does not need to be complete Compliance criteria:	If "yes", A below is required If "yes", B below is required
<u>4.</u>	Operating permit and nitrogen BMP* – Compliance component #4 of Is the system operated under an Operating Permit? □ Yes □ No Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be complete Compliance criteria: a. Have the operating permit requirements been met? □ Yes □ No	If "yes", A below is required If "yes", B below is required
<u>4.</u>	Operating permit and nitrogen BMP* – Compliance component #4 of Is the system operated under an Operating Permit? □ Yes □ No Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be complete Compliance criteria: a. Have the operating permit requirements been met? □ Yes □ No b. Is the required nitrogen BMP in place and properly functioning? □ Yes □ No	If "yes", A below is required If "yes", B below is required
<u>4.</u>	Operating permit and nitrogen BMP* – Compliance component #4 of Is the system operated under an Operating Permit? □ Yes □ No Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be complete Compliance criteria: a. Have the operating permit requirements been met? □ Yes □ No b. Is the required nitrogen BMP in place and properly functioning? □ Yes □ No Any "no" answer indicates noncompliance.	If "yes", A below is required If "yes", B below is required

Attached supporting documentation:
Operating permit (Attach)

5. Soil separation – Compliance component #5 of 5


	011 m/dd/yyyy)	Unkn	iown			
Shoreland/Wellhead protection/Food beverage lodging?		🛛 Yes	🗌 No	Attached supporting documentation:		
Compliance criteria (s	select one):			Two previous verifications of required	vertical separation	
5a.For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment:		☐ Yes	🗌 No*	Not applicable (No soil treatment area)	
Drainfield has at least separation distance fro saturated soil or bedro	om periodically					
5b.Non-performance systems built		🗌 Yes	🗌 No*	Indicate depths or elevations		
April 1, 1996, or later or for non- performance systems located in Shorel				A. Bottom of distribution media	100.95	
or Wellhead Protection food, beverage, or lod	n Areas or serving a			B. Periodically saturated soil/bedrock	97.9	
Drainfield has a three- separation distance fro				C. System separation	3.05	
saturated soil or bedro				D. Required compliance separation*	2.55	
				*May be reduced up to 15 percent if allo Ordinance.	wed by Local	
5c. "Experimental", "Other systems built under pr Type IV or V systems Rules 7080. 2350 or 7 (Intermediate Inspecto 2,500 gallons per day; License required > 2,5 Drainfield meets the de separation distance fro saturated soil or bedro	e-2008 Rules; built under 2008 080.2400 or License required ≤ Advanced Inspector 500 gallons per day) esigned vertical om periodically	⊠ Yes	□ No*			

*Any "no" answer above indicates the system is failing to protect groundwater.

Describe verification methods and results:

Upgrade requirements: (*Minn. Stat.* § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food,

beverage, and lodging establishments as defined in law.




2023 Septic Check Compliance



Sewer Design & Installation

JAROLD R. FARLEY

230 S. Maddy Street McGregor, MN 55760 218-768-3211 Bus. Lic. No. L1919 Reg. No. 4744 **218-839-4737** cell



Soil Observation Log

Soil Verifica	ation for:	Ukura's E	lig Dollar	Store			Property Addres	ess			
				√ C	Dutwash	Lacustrine	Loess Till	Alluvi	um Bedro	ock Organic	Matter
Landscape	Position: (ch	eck one)	Summi	t 🗌 Shou	ulder 🗌 Ba	ack/Side Slop	De 🗸 Foot Slop	Toe Slope			1
Vegetation	Vegetation Grass Soil survey map ur				nap units		ani Mo				
Weather Co	onditions/Time	e of Day:				10am-Clo	udy		Date	U	12/27/23
Observatio	on #/Location:				1			Observation ⁻	Туре:		Soil Pit
Depth (in)	Texture	Rock Frag. %	Matrix (Color(s)	Mottle	Color(s)	Redox Kind(s)	Indicator(s)	Shape	I Structur	eI Consistence
0-4	Sandy Loam	<35%	10YR	3/2					Granular	Strong	Friable
4-12	Loamy Fine Sand	<35%	10YR	4/6					Granular	Strong	Friable
12-18	Loamy Fine Sand	<35%	7.5YR	5/6	10YR	6/2	Concentrations, depletions	S1	Granular	Strong	Friable
Observation #/Location: 2				Observation Type: Auger		Auger					
Depth (in)	Texture	Rock	Matrix (Color(s)	Mottle	Color(s)	Redox Kind(s)	Redox Kind(s) Indicator(s)		I StructureI	
,		Frag. %							Shape	Grade	Consistence
0-4	Sandy Loam Loamy Fine	<35%	10YR						Granular	Strong	Friable
4-14	Sand	<35%	10YR	4/4			Orrestations		Granular	Strong	Friable
14-19	Loamy Fine Sand	<35%	7.5YR	5/6	10YR	6/2	Concentrations, depletions	S1	Granular	Strong	Friable
Observatio	on #/Location:				3			Observation Type: Auger		Auger	
Depth (in)	Texture	Rock	Matrix (Color(s)	Mottle	Color(s)	Redox Kind(s)	Indicator(s)		I Structur	·el
	Texture	Frag. %	Maurix		Mottle			indicator(3)	Shape	Grade	Consistence
0-3	Sandy Loam	<35%	10YR	3/2					Granular	Strong	Friable
3-10	Loamy Fine Sand	<35%	10YR	5/4			0		Granular	Strong	Friable
10-15	Loamy Fine Sand	<35%	7.5YR	5/8	7.5YR	6/2	Concentrations, depletions	S1	Granular	Strong	Friable
Observatio	on #/Location:							Observation ⁻	Туре:		Auger
Depth (in)	Texture	Rock	Matrix (Color(s)	Mottle	Color(s)	Redox Kind(s)	Indicator(s)		I Structur	
		Frag. %	matrix						Shape	Grade	Consistence

SAMPLING REPORT

Location: 41561 State Hwy 65 McGregor **14-0-041802**

owner: Ukura's Big Dollar Store use: Food Establishment

Service Company: Septic Check

6074 Keystone Rd Milaca, MN 56353 320-983-2447

Laboratory: A W Labs

Sample Date: 05/23/2023 Sample entered by: Heather Johnson Report submitted: 06/01/2023

Notes:

ONSITE SEWAGE SYSTEM SAMPLING DETAIL								
COMPONENT	TYPE	SAMPLE	LIMIT	RESULT				
Control - 2 Pumps	Effluent	Flow	1200 GPD	337.9				
Pump Tank 1960 Gallon With Eff. Filters	Effluent	CBOD	125 mg/l	49				
Pump Tank 1960 Gallon With Eff. Filters	Effluent	TSS	65 mg/l	21.3				

This report indicates certain characteristics of the sample taken at the time of visit. In no way is this report a guarantee of operation or future performance.

SAMPLING REPORT

Location: 41561 State Hwy 65 McGregor **14-0-041802**

owner: Ukura's Big Dollar Store use: Food Establishment

Service Company: Septic Check 6074 Keystone Rd

Milaca, MN 56353 320-983-2447

Sample Date: 10/12/2023 Sample entered by: Heather Johnson Report submitted: 11/01/2023

Notes:

ONSITE SEWAGE SYSTEM SAMPLING DETAIL									
COMPONENT	TYPE	SAMPLE	LIMIT	RESULT					
Control - 2 Pumps Effluent Flow 1200 GPD 306.13									

This report indicates certain characteristics of the sample taken at the time of visit. In no way is this report a guarantee of operation or future performance.

Septic Check

6074 Keystone Rd Milaca, MN 56353

Mail To: Ukura's Big Dollar Store

P.O. BOX 97

55760

McGregor, MN

Septic Check

320-983-2447 Fax: 320-983-2151

Fold

Here

~ PROPERTY INFORMATION

Location: 41561 State Hwy 65 McGregor Tax ID: 14-0-041802

> Use: Commercial, Food Establishment System Design Flow: 1200 GENERAL SYSTEM TYPE: VBT Comm 2 w test

> > Heather Johnson

Fold Here

UN-SITE WASTEWATER TH	XEATMENT STSTEM INSPECTION REPORT	
Inspected: 05/23/2023 - Inspectio	n Type: ROUTINE - Correction Status: Corrections in progress	
Company:	Work Performed By:	Submitted 05/25/2023 by:

RITE WARTEWATED TREATMENT RVRTEM INRRETION REPOR

COMMENTS & GENERAL INSPECTION NOTES

No Deficiencies Noted

found that there was 18" of sludge in the first septic tank.	
I would recommend pumping out the first septic tank.	
Everything else seemed to be working properly.	

Kyle Wade

GENERAL SITE & SYSTEM CONDITIONS

The General Site and System Conditions were:	Fully Inspected
Components accessible for service:	YES
All required service performed (if no - specify omitted inspection items in notes):	YES
Surfacing effluent from any component (including mound seepage):	NO
Components appear to be watertight - no visual leaks:	YES
Improper encroachment (structures/impervious surfaces); cover; or settling problems observed:	NO

ONSITE SEWAGE SYSTEM INSPECTION DETAIL

TANK: Septic Tank - 1 Compartment, Manufacturer= Local Manufacturer - Concrete 1 - 1960 Gal	lon	
Manufacturer: Local Manufacturer Model: Concrete		
This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	1	
Compartment 1 Sludge accumulation (Inches, if other specify):	18	
Pumping recommended:	YES	
TANK: Septic Tank - 1 Compartment, Manufacturer= Local Manufacturer - Concrete 2 - 1960 Gal	lon	
Manufacturer: Local Manufacturer Model: Concrete		
This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	8	
Pumping recommended:	NO	
TANK: Septic Tank - 1 Compartment, Manufacturer= Local Manufacturer - Concrete 3 - 1960 Gal	lon with VBT	
Manufacturer: Local Manufacturer Model: Concrete		
This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
All required baffles in place (N/A = No baffles required):	YES	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	9	
Pumping recommended:	NO	
TANK: Pump Tank, Manufacturer= Local Manufacturer - Concrete 1960 Gallon With Eff. Filters		
Manufacturer: Local Manufacturer Model: Concrete		
This component was:	Fully Inspected	
Compartment 1 Scum accumulation (Inches, if other specify):	0	
Compartment 1 Sludge accumulation (Inches, if other specify):	0	
Pumping recommended:	NO	

Aerobic Treatment Unit: ATU, Manufacturer= Advanced Aeration - VBT 200 VBT 200-20		
Manufacturer: Advanced Aeration Model: VBT 200		
This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
Aerobic Mechanism appears to be functioning per manufacturers specifications:	YES	
ATU serviced per manufacturers requirements including cleaning of applicable filter(s):	YES	
Trash Compartment solids accumulation within operational limits per manufacturer (n/a = no trash	N/A	
compartment):		
Aerobic Chamber solids accumulation within manufacturer operational limits (n/a = no aerobic chamber):	YES	
Clarifying Chamber solids accumulation within manufacturer operational limits (n/a = no clarifying	N/A	
chamber):		
Pumping recommended:	NO	
Pump: Effluent Pump, Manufacturer= Zoeller Pump Co other Pump 1 Zoeller 153		
Manufacturer: Zoeller Pump Co. Model: other		
This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	
Pump: Effluent Pump, Manufacturer= Zoeller Pump Co other Pump 2 Zoeller 153		
Manufacturer: Zoeller Pump Co. Model: other		
This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	
Panel: Control - 2 Pumps		
This component was:	Fully Inspected	
Panel functioning (including alarm):	YES	
Pump 1: on minutes (override in parentheses - if present):	3 min 13 sec	
Pump 1: off hours (override in parentheses - if present):	2	
Pump 1: gallons per dose (override in parentheses - if present):	-	
Pump 1: ETM hours (override in parentheses - if present):	226.28	
Pump 1: Cycle Count (override in parentheses - if present):	4259	
Pump 2: on minutes (override in parentheses - if present):	3min 13 sec	
Pump 2: off hours (override in parentheses - if present):	2	
Pump 2: gallons per dose (override in parentheses - if present):	-	
Pump 2: ETM hours (override in parentheses - if present):	344.43	
Pump 2: Cycle Count (override in parentheses - if present):	6475	
Drainfield (disposal): Pressure Bed Two 10' x 50' rockbed mound		
This component was:	Fully Inspected	
Lateral lines flushed:	NO	
Average squirt height (if performed) (feet, if other specify):	-	
Ponding present? If YES explain in comments:	NO	

This report indicates certain characteristics of the onsite sewage system at the time of visit. In no way is this report a guarantee of operation or future performance.

Septic Check

6074 Keystone Rd Milaca, MN 56353

Mail To: Ukura's Big Dollar Store

P.O. BOX 97

55760

McGregor, MN

320-983-2447 Fax: 320-983-2151

> Fold Here

C PROPERTY INFORMATION

Location: 41561 State Hwy 65 McGregor Tax ID: 14-0-041802

> Use: Commercial, Food Establishment System Design Flow: 1200 GENERAL SYSTEM TYPE: VBT Comm 2 w test

Fold Here

ON-SITE WASTEV	VATER TREATMENT SYS	TEM INSPECTION REPORT
1		

Inspected: 10/12/2023 - Inspection Type: ROUTINE - Correction	Status: Corrections in progress	
Company:	Work Performed By:	Submitted 11/01/2023 by:
Septic Check	Matt Maleski	Heather Johnson

COMMENTS & GENERAL INSPECTION NOTES

No Deficiencies Noted

- We recommend having the complete system pumped as it is due.	
- We will also replace the effluent filter that is not accessible with the correct one that is in the design. (If approved)	
- Everything else is working properly at the time of service.	

GENERAL SITE & SYSTEM CONDITIONS

The General Site and System Conditions were:	Fully Inspected	
Components accessible for service:	YES	
All required service performed (if no - specify omitted inspection items in notes):	YES	
Surfacing effluent from any component (including mound seepage):	NO	
Components appear to be watertight - no visual leaks:	YES	
Improper encroachment (structures/impervious surfaces); cover; or settling problems observed:	NO	

ONSITE SEWAGE SYSTEM INSPECTION DETAIL

TANK: Septic Tank - 1 Compartment, Manufacturer= Local Manufacturer - Concrete 1 - 1960	Sallon
Manufacturer: Local Manufacturer Model: Concrete	Sanon
This component was:	Fully Inspected
Effluent level within operational limits (if NO explain in comments):	YES
All required baffles in place (N/A = No baffles required):	YES
Compartment 1 Scum accumulation (Inches, if other specify):	2
Compartment 1 Sludge accumulation (Inches, if other specify):	18
Pumping recommended:	YES
TANK: Septic Tank - 1 Compartment, Manufacturer= Local Manufacturer - Concrete 2 - 1960 (Gallon
Manufacturer: Local Manufacturer Model: Concrete	
This component was:	Fully Inspected
Effluent level within operational limits (if NO explain in comments):	YES
All required baffles in place (N/A = No baffles required):	YES
Compartment 1 Scum accumulation (Inches, if other specify):	0
Compartment 1 Sludge accumulation (Inches, if other specify):	16
Pumping recommended:	YES
TANK: Septic Tank - 1 Compartment, Manufacturer= Local Manufacturer - Concrete 3 - 1960 (Gallon with VBT
Manufacturer: Local Manufacturer Model: Concrete	
This component was:	Fully Inspected
Effluent level within operational limits (if NO explain in comments):	YES
All required baffles in place (N/A = No baffles required):	YES
Compartment 1 Scum accumulation (Inches, if other specify):	0
Compartment 1 Sludge accumulation (Inches, if other specify):	12
Pumping recommended:	YES
TANK: Pump Tank, Manufacturer= Local Manufacturer - Concrete 1960 Gallon With Eff. Filter	s
Manufacturer: Local Manufacturer Model: Concrete	
This component was:	Fully Inspected
Compartment 1 Scum accumulation (Inches, if other specify):	0
Compartment 1 Sludge accumulation (Inches, if other specify):	2
Pumping recommended:	NO

Aerobic Treatment Unit: ATU, Manufacturer= Advanced Aeration - VBT 200 VBT 200-20		
Manufacturer: Advanced Aeration Model: VBT 200		
This component was:	Fully Inspected	
Effluent level within operational limits (if NO explain in comments):	YES	
Aerobic Mechanism appears to be functioning per manufacturers specifications:	YES	
ATU serviced per manufacturers requirements including cleaning of applicable filter(s):	YES	
Trash Compartment solids accumulation within operational limits per manufacturer (n/a = no trash	N/A	
compartment):		
Aerobic Chamber solids accumulation within manufacturer operational limits (n/a = no aerobic chamber):	N/A	
Clarifying Chamber solids accumulation within manufacturer operational limits (n/a = no clarifying	N/A	
chamber):		
Pumping recommended:	NO	
Pump: Effluent Pump, Manufacturer= Zoeller Pump Co other Pump 1 Zoeller 153		
Manufacturer: Zoeller Pump Co. Model: other		
This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	
Pump: Effluent Pump, Manufacturer= Zoeller Pump Co other Pump 2 Zoeller 153		
Manufacturer: Zoeller Pump Co. Model: other	1 1	
This component was:	Fully Inspected	
Controls functioning:	YES	
Tested gallons per minute flow:	-	
Panel: Control - 2 Pumps		
This component was:	Fully Inspected	
Panel functioning (including alarm):	YES	
Pump 1: on minutes (override in parentheses - if present):	3.13	
Pump 1: off hours (override in parentheses - if present):	2.00.00	
Pump 1: gallons per dose (override in parentheses - if present):	-	
Pump 1: ETM hours (override in parentheses - if present):	233.15	
Pump 1: Cycle Count (override in parentheses - if present):	4386	
Pump 2: on minutes (override in parentheses - if present):	2.13	
Pump 2: off hours (override in parentheses - if present):	2.00.00	
Pump 2: gallons per dose (override in parentheses - if present):	-	
Pump 2: ETM hours (override in parentheses - if present):	351.23	
Pump 2: Cycle Count (override in parentheses - if present):	6600	
Drainfield (disposal): Pressure Bed Two 10' x 50' rockbed mound		
This component was:	Fully Inspected	
Lateral lines flushed:	NO	
Average squirt height (if performed) (feet, if other specify):	-	
Ponding present? If YES explain in comments:	NO	

This report indicates certain characteristics of the onsite sewage system at the time of visit. In no way is this report a guarantee of operation or future performance.



Vacation/Private Home Rental App. # App-2023-001347, UID # 209431 App. Status: Pending Review

Meeting date: 1/20/24 Date complete: 12/14/23 60 day: 2/11/24

Contact Information

Aitkin County Planning & Zoning / Environmental Services 307 2nd Street NW, Room 219 Aitkin, MN 56431 Phone: 218-927-7342 Fax: 218-927-4372 Email: aitkinpz@co.aitkin.mn.us

If we have questions on the application who should we contact?	Name: Michelle Goltz Phone: (612) 685 - 0470 Email Address: michellegoltz@gmail.com Mailing Address: 48565 216th Place McGregor MN 55760
I the property owner?	Yes
Do you have a contact person that meets all requirements of Section	Yes
ning Ordinance?	

12/26/23, 12:07 PM

Project Location Search

Property:	Property Location			Legal Description			Property Attributes		Owner Information	Tax Payer Information
	Parcel Number	Property Address	Township or City Name	Legal Description	Plat Name	Section- Township- Range	Lake Class	Lake Name	Owner Name(s)	Taxpayer Name(s)
	29-0- 040607	48565 216TH PL MCGREGOR MN 55760	SHAMROCK TWP	PART LOT 4 IN DOC 422677 (PARCEL B)		S:19 T:49 R:23	RD	SANDY	GOLTZ, MICHELLE M	GOLTZ, MICHELLE M
Driving directions to the property from Aitkin:	From Aitkin	210 to Hwy 65 nort	h. Left at 216th P	lace (across from zorbaz	parking l	ot). Home on right				

12/26/23, 12:07 PM

Brief Narrative

OneGov

Brief Narrative:	Rustic Luxury Retreat: 3BR/3BA, Stone Fireplace, Modern Amenities Escape to our enchanting 3-bedroom, 3-bathroom retreat, where rustic charm meets modern luxury. Nestled in the heart of nature, this haven boasts wood frame architecture, a captivating stone fireplace, and breathtaking views visible through large windows that bathe the space in natural light. With 9-foot ceilings, a sprawling deck, and all the modern amenities you crave, this is your sanctuary in the wilderness. There are tons of amazing local establishments including Zorbaz, MN National Golf Course, Big Sandy Lodge, The Sandy Beaver, Craft House and Banns Bar and Grill.
List all current advertising sources: (Be specific and include website links, rental ID #'s, title, etc.) All advertising must be in compliance with the occupancy allowance and all other conditions of the permit. Notify Environmental Services with any changes to the advertising within 30 days.	Will be advertising on Airbnb. Vacation rental - 7 day stays or longer. I am very familiar with Airbnb rentals in this area as I had one on Big Sandy a couple of years ago at 22126 512th Lane, McGregor.
Proposed occupancy of overnight guests:	6
How many rental units will be located on this parcel?	1
Will you be renting for periods of less than one week?	No
Quiet hours will begin at:	10 : 00 <u>PM</u>
Quiet hours will end at:	09 : 00 <u>AM</u>

12/26/23,	12:07 PM
-----------	----------

Floor Plan of Structure

 Please attach a floor plan of the rental unit that includes the following: Label sleeping areas with dimensions Location of egress windows and doors Location of all smoke alarms and carbon monoxide alarms 	File 1: 🚽 21201.pdf File 2: 🚽 Home_plan_with_smokes_co2_and_fire_extinguisher.pdf
2. How many rooms will be used for sleeping?	<u>3</u>
3. How many carbon monoxide alarms are located in the rental?	3
4. How many smoke detector alarms are located in the rental?	6
5. A fire extinguisher must be placed in an easily accessible location within each rental unit. Where is the fire extinguisher located?	Under kitchen sink

OneGov

Sleeping Area #1

Was this window installed before July 10, 2007?	No
Select Window style. (see attached diagram for window style options):	Exterior Door/Patio Door
What is the OPENABLE height of this window:	93 inches
What is the OPENABLE width of this window:	35 inches
What is the distance from the floor to the bottom of this window (finished sill):	1 inches

Sleeping Area #2

Was the largest window in this room installed before July 10, 2007?	No
Select window style. (see attached diagram for window style options):	Casement
What is the OPENABLE height of this window?	68 inches
What is the OPENABLE width of this window?	34 inches
What is the distance from the floor to the bottom of this window (finished sill)?	18 inches

Sleeping Area #3

Was the largest window in this room installed before July 10, 2007?	No
Select window style. (see attached diagram for window style options):	Casement
What is the OPENABLE height of this window?	68 inches
What is the OPENABLE width of this window?	34 inches
What is the distance form the floor to the bottom of this window (finished sill)?	18 inches

Scaled Site Plan

Please attach your scaled site plan:	File 1: 🖶 Big_sandy_hive.pdf	

OneGov

Emergency Contact Info

Police:	(218) 927 - 7359
Fire:	(218) 768 - 2717
Hospital:	(218) 927 - 2121
Septic Tank Pumper:	(218) 927 - 6175
Where in the rental will the emergency contact information be posted?	On the Center Island in the manual for the home. In most cases we will recommend to call 911 for police or fire

Property Information Handbook

Please select all that will be included in your handbook:	Name & contact information for owner and/or caretaker Quiet hours Maximum # of overnight guests Maximum # of non-overnight guests Property rules related to outdoor features List of conditions placed on the approved IUP Notice that all ordinances and IUP conditions will be enforced by the Aitkin County Sheriff's Office and the Aitkin County Environmental Services Department
Where in the rental will your handbook will be located?	On the center island in the kitchen

Septic Compliance

Attach septic compliance:	Goltz_Michelle_1.pdf	
	L	

Water Test Results

Attach Water Test:	File 1: 🖶 23-13343_L23-51.pdf	
Allach Walch Test.	File 2: 🖶 rptTestReportLetter.pdf	

12/26/23, 12:07 PM

Garbage Disposal Plan

How often will the garbage be collected?	Weekly
Please enter the name of the garbage collection service or describe your disposal plan:	Countryside Sanitation

Pet Policy

Pet Policy:	No pets allowed
-------------	-----------------

Property Deed

]

Terms

Interior & Exterior Inspection

After your submitted application is accepted by Environmental Services, a staff member will contact you to schedule an interior inspection to verify the information provided in your application. It is the responsibility of the applicant to have the following in place prior to the inspection:

1. Smoke alarms and carbon monoxide alarms installed per MN State Fire Code

2. Fire extinguishers are in their designated places and meeting MN State Fire Code

3. Flow-measuring device installed on the septic system or well

4. Visual demarcations of the property lines

Shamrock Township Lodging Tax Ordinance

If the proposed VRBO is located within Shamrock Township, please be aware there is a Lodging Tax Ordinance that will apply to this rental. For more information, please contact Shamrock Township at (218) 426-3736.

General Terms

The landowner or authorized agent hereby certifies that to the best of their knowledge the application and supporting documents are a factual representation of the proposed project. The landowner or authorized agent agrees that, in making application, the landowner grants permission to Aitkin County, at reasonable times, to enter the property to determine compliance of the application with applicable Local, County or State Ordinances or Statutes. It is the applicant's responsibility to contact other Local, County or State agencies to ensure the applicant has complied with all relevant Local, County or State Ordinances or Statutes.

Submittal of the above materials does not always constitute a complete application. Other information may be necessary to complete the application based on the type of request and onsite inspection.

I acknowledge that by submitting this application, the application and its attachments are public information.

Invoice #59100 (12/14/2023) Expected Payment Method: Pay Online - Card or ECheck

Charge	Cost	Quantity	Total
Recording Fee added 12/14/2023 2:30 PM This fee is non-refundable if denied.	\$46.00	x 1	\$46.00
Vacation/Private Home Rental added 12/14/2023 2:30 PM This fee is non-refundable if denied.	\$650.00	x 1	\$650.00
Grand Total			
		Total	\$696.00
		Payment 12/05/2023	\$696.00
		Due	\$0.00

Approvals

Approval	Signature
Applicant	Michelle Goltz - 12/14/2023 2:36 PM - witnessed by Connor Plagge
	aab7d104790302f9a0066ce84060f434
	8ecbf83c5a223a98735bcb8e1b41a779
#1 Administrative Staff	Connor Plagge - 12/18/2023 12:30 PM
	f8a9c0f9c2ca1a3ada96e642643aead9
	86a381c5c2cddb1c676eef604376fbb2
#2 Planning Commission	


Public Notes


Text:	To be heard at the January 22nd, 2024 Planning Commission meeting.	
File(s):		
	1	


Administrative Staff


This review has been started by:	Connor Plagge V
Zoning District:	Shoreland V
Is the parcel a Lot of Record before 1-21-92 or have alternate sites been identified?	Yes 🗸
Is this an After-The-Fact application?	No 🗸
Current SSTS:	Mound (Type I)
Max Overnight Guests per SSTS:	6


Print View























CROSS SECTION "D" 1/4"=1'-@'

o⊧ 8 CADD FILE * 21201







AITKIN COUNTY CERTIFICATE OF INSTALLATION/NOTICE OF NONCOMPLIANCE

This certificate of installation/notice of noncompliance has been issued this <u>7th</u> day of <u>July</u>, 20<u>22</u> to certify compliance\noncompliance with Aitkin County's Subsurface Sewage Treatment System Ordinance. The premises covered by this certificate are legally described as: <u>Part of lot 4 in doc 422677 (parcel B)</u>

 Section 19
 Township 49
 Range 23
 Lake Sandy River Lake

 PERMIT NO. 47047
 Owner Name Michelle Goltz

Address 48565 216th PI McGregor, Mn 55760

Installer Name Wruck Excavating

Type of System Inspected <u>3 Bdrm Type I Mound</u>

Parcel Number <u>29-0-040607</u>

The certificate of installation/notice of noncompliance was based on No 1 of the following:

1) Inspection of the installation or construction as in accordance with the above referenced permit and application design.

2) Review of as-built plans submitted in accordance with Subdivision 9.2 D of Aitkin County's Subsurface Sewage Treatment System Ordinance.

If the above permitted subsurface sewage treatment system is in noncompliance with Aitkin County's Subsurface Sewage Treatment System Ordinance, then the following shall serve as a Notice of Violation:

1) Statement of the findings of fact through inspections or investigations:

2) List of specific violations of Ordinance:

3) Requirements for correction or removal of violations:

4) Time schedule for compliance:

Failure to correct or remove the above violation(s) will result in this matter being turned over to the Aitkin County Attorney's Office for further legal action, which may result in revocation of licenses, fines and/or imprisonment.

INSPECTOR SIGNATURE - Inmoch



617 13th Ave S.; Hopkins, MN 55343 (952) 935-3556 tcwaterclinic@gmail.com

Drinking Water Laboratory Test Report

Report M	Report lesue Date:
23-13343	12/13/2023
CLIENT INFORMATION	
CLIENT/CLIENT ADDRESS:	OWNER/OWNER ADDRESS:
Field Engineering Inc 7608 119th Ln N Champlin, MN 55316	Michelle Gołtz
WELL #/	48565 216th PLMcGregor, MN WELL ADDRESS:
	48565 216th PI McGregor, MN
SAMPLE RESULTS	
DATE/TIME COLLECTION OF SAMPLE:	DATE/TIME OF SAMPLE RECEIPT:
12/11/2023 - 9:00	12/12/2023 - 11:00
SAMPLE RECEIVED ON ICE:	TEMP. OF SAMPLE UPON RECEIPT:
🕅 YES 📋 NO	5°-C
SAMPLE COLLECTION POINT.	COLLECTED BY:
Kitchen tap	🔲 TCWC 📋 CLIENT 🛛 🖉 OTHER
SAMPLE RESULTS	
LABORATORY SAMPLE ID:	CLIENT ID:
23-13343	L23-51
	MCL ANALYSIS DATE ANALYSIS TIME METHOD
ANALYTE PASS/FAIL? Pesuk	MCL ANALYSIS DATE ANALYSIS TIME METHOD

Total Coliform	PASS √	ABSENT	<1 cfu/100mL	12/12/2023	13/11	SM92228 (M-Endlo) • © (EC MUG) -97
Nitrate as N	PASS 🗸	<1.0 mg/L	10 mg/L	12/12/2023	13:58	EPA 353.2 Rev 2,0

The analyte(s) reported, for the above (isted sample(s) pass if the result is below the MCL (maximum contaminant level) and fail if the result is above the MCL. The MCL is set by the U.S. EPA and followed by the Minnesota Department of Health for safe drinking water.

NOTES

APPROVED BY:

A.C.

Bill VanArsdale - Lab Manager

Page 1 of 1

Minnesota Laboratory ID # 027-053-119

The results listed in the report. Apply only active above listed samples. All routine quality assurance procedures were followed unless otherwise noted. The analytical report must be reported in its entirety. All methods are certified by the Minnessee Department of Health unless otherwise noted.

Rev 1- 4/2023

Field Engineering, Inc.

WATER ANALYSIS 7608 119th Lane North - Champlin, Minnesota 55316

> Telephone: 763-427-0826 FED. ID # 411443773

13 December 2023

162128
9:00 AM
Kitchen tap
11 December 2023
12 December 2023
Brought in
23-13343 L23-51

To: MICHELLE GOLTZ 48565 216TH PL MCGREGOR, MN 55760

RE: Water test at:48565 216TH PL; MCGREGOR, MN

Field Engineering personnel in conjunction with Twin City Water Clinic tested the water that was drawn by Michelle Goltz at the above address and the results were as follows:

Test	<u>Maximum limit</u>	<u>Results</u>	<u>Remarks</u>
Coliform Bacteria - SM9222B	Absent	Absent	
Nitrate Nitrogen - SM4500	10 mg/L	less than 1.0 mg/L	

This water DOES meet state, conventional, FHA, VA, and U.S.P.H.S. guidelines for the tests listed above. Twin City Water Clinic is certified to perform these tests by the Minnesota Department of Health certificate #027-053-119 and Wisconsin Department of Agriculture certificate #105-10117. This report must not be reproduced, except in full, without the written approval from Twin City Water Clinic and Field Engineering, Inc.

Sincerely Yours,

Margie Koerner

Margie Koerner

DETACH AND RETURN WITH PAYMENT

Field Engineering, Inc.

WATER ANALYSIS 7608 119th Lane North - Champlin, Minnesota 55316 Telephone: 763-427-0826 FED. ID # 411443773

To: MICHELLE GOLTZ 48565 216TH PL

13 December 2023

MCGREGOR, MN 55760

RE: Water test at 48565 216TH PL; MCGREGOR, MN

Test No 162128 Unique #: Brought in

Amount paid: \$70.00

Thank you for using Field Engineering for your water testing needs.

CRV Filed Auditor's CRV # 48559 No Delinquent Taxes and Transfer Entered Kirk Peysar, County Auditor State Deed Tax Paid Lori Grams, County Treasurer

Doc No: A464251

WAD 1/2

Certified Filed and/or Recorded on SDT 5/26/2021 9:00 AM

REC FEE \$46.00 SDT \$280.17 eCRV # 1255958

.

Office of the County Recorder Aitkin County, Minnesota Michael T. Moriarty, County Recorder

Package: 72207 Tara

	(Top 3 inches reserved for recording data)
WARRANTY DEED Individual(s) to Indivi	dual(s)	Minnesota Uniform Conveyancing Blanks Form 10.1.1 (2018)
eCRV number:	55958	
DEED TAX DUE: \$ 2	30.17	DATE: <u>5/24/202/</u> (month/day/year)
FOR VALUABLE CON spouses married to e		nson, a single person, and Jason R. Kadelbach and Christina L. Kadelbach, (insert meme and marital status of each Grantor)
spouses married to e	saurionar	("Grantor"),
hereby conveys and w	arrants to _Michelle M. Golt	Z
		(insert name of each Grantee)("Grantee"), as
(Check only one box.)	tenants in common, joint tenants,	(If more than one Grantee is named above and either no box is checked or both boxes are checked, this conveyance is made to the named Grantees as tenants in common.)
real property in <u>Aitkin</u> See attached Exhibi	t A for legal description.	County, Minnesota, legally described as follows:

Check here if all or part of the described real property is Registered (Torrens) \Box

•

together with all hereditaments and appurtenances belonging thereto, subject to the following exceptions: reservations, restrictions and easements of record, if any.

Check applicable box:

- The Seller certifies that the Seller does not know of any wells on the described real property.
- A well disclosure certificate accompanies this document or has been electronically filed. (If electronically filed, insert WDC number;
- I am familiar with the property described in this instrument and I certify that the status and number of wells on the described real property have not changed since the last previously filed well disclosure certificate.

Grantor		
0		
(signature) Ada	n J. Hanson	
	Marce	
(signatyre) Jaso	on R. Kadelbach	
And	timp d. Kadullace	ン

(signature)

State of Minnesota, County of Aitkin

This instrument was acknowledged before me on <u>May 24, 2021</u>, by <u>Adam J. Hanson, a single person, and Jason</u> (month/da//yea/)

R. Kadelbach and Christina L. Kadelbach, spouses married to each other

(Insert name and marital status of each Granior)

(Stamp)

rist officer)

Title (and Rank):

My commission expires: _

(month/day/year)

TAX STATEMENTS FOR THE REAL PROPERTY DESCRIBED IN THIS INSTRUMENT SHOULD BE SENT TO: (Insert legel mame and residential or business address of Grantee) Michelle M. Goltz 15040 Partridge St NW Andover, MN 55304

AMANDA T. MCCARTAN NOTARY PUBLIC-MINNESOTA My Comm. Exp. Jan. 31, 2022

THIS INSTRUMENT WAS DRAFTED BY: (insert name and address)

Esquire Title Service, LLC 204 2nd Street NW Aitkin, MN 56431

21-1090

⁽signature) Christina L. Kadelbach

Exhibit "A"

That part of Government Lot 4, Section 19, Township 49 North, Range 23 West, Aitkin County, Minnesota, described as follows: Commencing at the Southeast corner of said Government Lot 4; thence South 85 degrees 01 minutes 01 seconds West, assumed bearing, a distance of 757.49 feet along the South line of said Government Lot 4 to the Northeast corner of Lot 1, Sather's Plat of Big Sandy Lake Narrows, according to the recorded plat thereof; thence North 03 degrees 10 minutes 40 seconds West 20.01 feet; thence Northeasterly 192.28 feet along the arc of a tangential curve concave to the Southeast, having a radius of 283.60 feet and a central angle of 38 degrees 50 minutes 47 seconds; thence North 35 degrees 40 minutes 07 seconds East; tangent to said curve, a distance of 320.32 feet; thence North 30 degrees 37 minutes 00 seconds East 151.58 feet; thence North 30 degrees 38 minutes 30 seconds East, 151.61 feet to the point of beginning; thence North 28 degrees 42 minutes 05 seconds East 150.94 feet; thence North 67 degrees 40 minutes 01 seconds West 391 feet, more or less, to the shore of Sandy River Lake; thence Southwesterly along said shore to a point which bears North 67 degrees 40 minutes 01 seconds West from the point of beginning; thence South 67 degrees 40 minutes 01 seconds East 384 feet, more or less, to the point of beginning.



Vacation/Private Home Rental App. # App-2023-001355, UID # 209401 App. Status: Pending Review

> Meeting date: 1/22/24 Date complete: 12/17/23 60 day: 2/14/24

Contact Information

Aitkin County Planning & Zoning / Environmental Services 307 2nd Street NW, Room 219 Aitkin, MN 56431 Phone: 218-927-7342 Fax: 218-927-4372 Email: aitkinpz@co.aitkin.mn.us

12/26/23, 12:12 PM

OneGov

Project Location Search

Property:	Property Location		Legal Description		Property Attributes		Owner Information	Tax Payer Information		
	Parcel Number	Property Address	Township or City Name	Legal Description	Plat Name	Section- Township- Range	Lake Class	Lake Name	Owner Name(s)	Taxpayer Name(s)
	26-0- 015400	18157 Driftwood St MCGREGOR, MN 55760	RICE RIVER TWP	NE NE & THE N 208.14 FT OF THE E 61.34 FT OF THE NW NE		S:10 T:46 R:23			LOR, MAY & DOUA	LOR, MAY & DOUA
Driving directions to the property rom Aitkin:	TAKE US-169 S (0.2 mile) TAKE HWY 47 S (8.7 miles) Left turn to HWY 4/Dam Lake St (Glen/Kimberly town hall) (7.1 miles) Left turn to HWY 65 N (2.1 miles) Right turn HWY 57/Driftwood St (3.1 miles) Follow Driftwood St to 18157 Driftwood									

Brief Narrative

OneGov

Brief Narrative:	I am requesting an Interim Use Permit to operate a vacation rental at our cabin home in McGregor. The capacity is 4 guests (2 bedrooms, 1 bathroom). Rentals will be year-round for less than a month in duration. I will be providing a guest information book that has emergency contacts, local businesses, renta agreements, etc. I will be advertising through Airbnb.com, VRBO.com, booking.com. Doua Lor (owner) will be the property management.		
List all current advertising sources: (Be specific and include website links, rental ID #'s, title, etc.) All advertising must be in compliance with the occupancy allowance and all other conditions of the permit. Notify Environmental Services with any changes to the advertising within 30 days.	Have not advertised the property yet.		
Proposed occupancy of overnight guests:	4		
How many rental units will be located on this parcel?	1		
Will you be renting for periods of less than one week?	Yes		
Quiet hours will begin at:	10 : 00 <u>PM</u>		
Quiet hours will end at:	08 : 00 <u>AM</u>		

12/26/23,	12:12	ΡM
-----------	-------	----

Floor Plan of Structure

1. Please attach a floor plan of the rental unit that includes the following: Label sleeping areas with _____ File 1: 🖶 Floor_Plan.docx dimensions Location of egress windows and doors Location of all smoke alarms and carbon monoxide alarms 2. How many rooms will be used for 2 sleeping? 3. How many carbon monoxide 5 alarms are located in the rental? 4. How many smoke detector 5 alarms are located in the rental? 5. A fire extinguisher must be placed in an easily accessible location Middle post between kitchen, dinning, and living room within each rental unit. Where is the fire extinguisher located?

Sleeping Area #1

Was this window installed before July 10, 2007?	Yes
Select Window style. (see attached diagram for window style options):	Sliding
What is the OPENABLE height of this window:	44 inches
What is the OPENABLE width of this window:	21 inches
What is the distance from the floor to the bottom of this window (finished sill):	35 inches

Sleeping Area #2

Was the largest window in this room installed before July 10, 2007?	Yes
Select window style. (see attached diagram for window style options):	Sliding
What is the OPENABLE height of this window?	44 inches
What is the OPENABLE width of this window?	21 inches
What is the distance from the floor to the bottom of this window (finished sill)?	35 inches

Scaled Site Plan



Emergency Contact Info

Police:	(218) 927 - 2133
Fire:	(218) 927 - 3303
Hospital:	(218) 927 - 2121
Septic Tank Pumper:	(218) 768 - 2575
Where in the rental will the emergency contact information be posted?	Left wall by entrance

12/26/23, 12:12 PM

OneGov

Property Information Handbook

Please select all that will be included in your handbook:	Name & contact information for owner and/or caretaker Quiet hours Maximum # of overnight guests Maximum # of non-overnight guests Property rules related to outdoor features List of conditions placed on the approved IUP
Where in the rental will your handbook will be located?	Notice that all ordinances and IUP conditions will be enforced by the Aitkin County Sheriff's Office and the Aitkin County Environmental Services Department on top of coffee table in the living room.

Septic Compliance

Attach septic compliance:	Septic_inspection.docx	

Water Test Results

Attach Water Test:	File 1: 🖶 Water_Test.docx	
	·	

Garbage Disposal Plan

How often will the garbage be collected?	Weekly
Please enter the name of the garbage collection service or describe your disposal plan:	Countryside Sanitation, LLC

Pet Policy

Pet Policy:	No Pets Allow
-------------	---------------

Property Deed

Attach the property deed:	File 1: - Property_Deed.docx	

Terms

Interior & Exterior Inspection

After your submitted application is accepted by Environmental Services, a staff member will contact you to schedule an interior inspection to verify the information provided in your application. It is the responsibility of the applicant to have the following in place prior to the inspection:

1. Smoke alarms and carbon monoxide alarms installed per MN State Fire Code

2. Fire extinguishers are in their designated places and meeting MN State Fire Code

3. Flow-measuring device installed on the septic system or well

4. Visual demarcations of the property lines

General Terms

The landowner or authorized agent hereby certifies that to the best of their knowledge the application and supporting documents are a factual representation of the proposed project. The landowner or authorized agent agrees that, in making application, the landowner grants permission to Aitkin County, at reasonable times, to enter the property to determine compliance of the application with applicable Local, County or State Ordinances or Statutes. It is the applicant's responsibility to contact other Local, County or State agencies to ensure the applicant has complied with all relevant Local, County or State Ordinances or Statutes.

Submittal of the above materials does not always constitute a complete application. Other information may be necessary to complete the application based on the type of request and onsite inspection.

I acknowledge that by submitting this application, the application and its attachments are public information.

OneGov

Invoice #59070 (12/17/2023) Expected Payment Method: Pay Online - Card or ECheck

Charge	Cost	Quantity	Total
Recording Fee added 11/28/2023 5:05 PM	\$46.00	x 1	\$46.00
This fee is non-refundable if denied.			
Vacation/Private Home Rental added 11/28/2023 5:05 PM	\$650.00	x 1	\$650.00
This fee is non-refundable if denied.			
Grand Total			
Total		\$696.00	
Payment 12/17/2023		\$696.00	
Due		\$0.00	

Approvals

Approval	Signature
Applicant	Doua Lor - 12/17/2023 11:52 PM
	af6e40b612aecbbab42e74a46918ce38
	5c4a879c7078cdb17eb708080861ec8f
#1 Administrative Staff	Connor Plagge - 12/19/2023 10:15 AM
	68159eda180c424471d83d0b8025ef97
	3f9b6f44041c31011313f07376e51e8a
#2 Planning Commission	

Public Notes

Text:	To be heard at the January 22nd, 2024 Planning Commission meeting.	
	Farm residential and shoreland zoning.	


OneGov

Filo(s):	
File(s):	[]

Administrative Staff

This review has been started by:	Connor Plagge V
Zoning District:	Farm Residential 🗸
Is the parcel a Lot of Record before 1-21-92 or have alternate sites been identified?	Yes 🗸
Is this an After-The-Fact application?	No 🗸
Current SSTS:	Mound (Type I)
Max Overnight Guests per SSTS:	4


Print View



18157 Driftwood St

Recently viewed

NORTH ST. FT WOOD WAY 5 wood storage 100 Juve 2 16 × 8' 9 è 8 PARKING shed 45' x 25' WOODED 14 x17' house gange propane Tank 55' x 34' 1 a well 30' fromgarage 25'x34' pea gravel patio 32' × 20' U 25' from house green hause 25' from house map M TO WOODED MG CP th GP [] septic Mound 60' From house N/ WOODED V GRASS 1,000, (10' x 26' Rock bed) Bridge B VD apan 25' × 10 M





Analysis

Report

November 16, 2023

INVOICE TO:

Lor, Doua

REPORT TO:

176 Haz	el St. N.
St. Paul	MN 55119

Date Rcvd-Brnd: Time Rcvd-Brnd:	11/14/2023 13:20		Sampled By: Sample Type: Recv Temp°C: TYPE:	Doua L DW 0.6 on i Well W	ce	LOCATION: Lor, Doua 18157 Driftwood St. McGregor MN	1 55760	
SITE / PERFORMED [Date/Time	Sample Result	Your Level	Units <i>TE</i>	Acceptable ST	Analytical Analyst	Analysis Methoo Code #	I Date/Time
Kitchen Tap-Softene	d 11/1	4/2023 @ 11	:40					
Coliform, Total Eschericha coli (E. coli) Nitrate, as N			ABSENT ABSENT < 0.100	/100mL /100mL mg/L	ABSENT ABSENT < 10	SM 9223 B (COLISURE)-2016 SM 9223 B (COLISURE)-2016 EPA 353.2 REV 2.0	11/14/23 15:32 11/14/23 15:32 11/14/23 16:05	CA 085048 CA 085048 MH 085048
Sample 085048: This sa	imple meets the S	State of Minnes	ota and EPA Guideli	ines for safe	Sala	Olley drinking water	for the analytes tested	1.

Approved By:Date Approved:

Sara Ahlers, Laboratory Director

A.W. Research Laboratories, Inc. is accredited by the MNELAP and follows approved methods and procedures. MN State Laboratory ID: 027-035-135 and EPA Lab Code: MN00098. All data generated using non-accredited methods noted as -NC, and all analytes for which accreditation is unavailable -NA. The results above relate only to the samples tested. This report must not be reproduced, except in full, without the written approval of the laboratory. We appreciate your feedback, please email us at awlab@awlab.com with questions or comments. Thank you!

11/16/2023

~End of Analysis Report~



Lab Report Code: 085048 Page 1 of 1

MINNESOTA POLLUTION Compliance inspection report

form CONTROL AGENCY

520 Lafayette Road North St. Paul, MN 55155-4194

Existing Subsurface Sewage Treatment System (SSTS)

Doc Type. Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (I-GU) and system owner within '1 5 days of final determination of compliance or noncompliance Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at https://www.pca.state.mn.us/sites/default/files/wq.,wwists4-31a.pdf. Property information Local tracking number:

Parcel or Secrrwp/Range. • 26-0-015400

Reason for Inspection App. for perm. Local regulatory authority info: Aitkin county planning and zoning Phone#218-927-7342

Property address: 18157 Driftwood St., McGregor, Mn.55760

Owner/representative: Doua Lor Owner's phone: 612-390-9591 Brief system description: 1860 gallon combo tank that pumps up into a 10' x 25' rock bed 1' sand base mound.

System status

System status on date (mm/dd/yyyy): 10/27/2023

Compliant — Certificate of compliance*

Noncompliant-Notice of noncompliance

use discontinued within the time required by local ordinance.

Systems failing to protect ground water must be upgraded, replaced, or

An imminent threat to public health and safety (ITPHS) must be upgraded,

replaced, or its use discontinued within ten months of receipt of this notice

(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)

*Note: Compliance indicates conformance with Minn.

or within a shorter period if required by local ordinance or under section R. 7080.1500 as of system status date above and does not 145A.04 subdivision 8. guarantee future performance.

Reason(s) for noncompliance (check all applicable)

Impact on public health (Compliance component #1) — Imminent threat to public health and safety Tank integrity (Compliance component #2) — Failing to protect groundwater

Other Compliance Conditions (Compliance component #3) — Imminent threat to public health and safety

C] Other Compliance Conditions (Compliance component #3) — Failing to protect groundwater System not abandoned according to Minn. R. 7080.2500 (Compliance component #3) - Failing to protect groundwater

Soil separation (Compliance component #5) - Failing to protect groundwater

Operating permit/monitoring plan requirements (Compliance component #4) — Noncompliant - local ordinance applies Comments or recommendations

Certification

I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage.

By typing my name below, I certify the above statements to be true and correct, to the best of my knowledge, and that this information can be

Property Address: 18157 Driftwood		
Business Name: Farley Sewer systems		Date: 10/27/2023
used for the purpose of processing this form.		
Business name: Farley Sewer systems	\wedge (Certification number: C-4744
Inspector signature: Jarold R. Farley	Ral	License number: L-1919
/ (This document has been	electronically signed)	Phone: 218-839-4737
Necessary or locally required sup	oporting documentation (must t	pe attached)
Soil observation logs System/As-Bui	It 🔲 Locally required forms 🔲 Tank Inte	grity Assessment
Other information (list):		
https://www.w/pca state mp us 651-296-6300 ° St.,McGregor,Mn.55760_	• 200-657-3264 • Use your preferred rela	ov service • Available in alternative formats of 4
1. Impact on public health — Co		
Com	liance criteria:Attac	ched supporting documentation:
System discharges sewage to the	Yes No C] Other: Not a	

Yes*

Yes

No

Any

"yes"

2. Tank integrity — Compliance component #2 of 5

answer above indicates the system is an imminent threat to

Com liance criteria:

System discharges sewage to drain

System causes sewage backup into

Describe verification methods and results:

tile or surface waters.

dwellin or establishment.

public health and safetyv_

Attached supporting documentation:

Property Address: 18157 Driftwood

	ness Name: Farley Sewer systems			— Date: 10/27/2023
	System consists of a seepage pit,	C] Yes	No	\boxtimes Empty tank(s) viewed by inspector
lame	cesspool, drywell, leaching pit, or other it?			of maintenance business: Kangas Ent.
-	Sewage tank(s) leak below their	Yes	No	License number of maintenance business: L- 1919
Date	designed operating depth?			of maintenance:10/27/2023
-				Existing tank integrity assessment (Attach)
	If es, which sewa e tank s leaks:			Date of maintenance
-	ii es, which se wa e tank s leaks.			(mm/dd/yyyy): (must be within three years)
	Any 'tyes ^Y ' answer above indicates t protect groundwater. Minn. R. 7082.	ha syster 0700 sub	n (See for p. 4 B (1))	m instructions to ensure assessment complies with js failing to
				Tank is Noncompliant (pumping not necessary — explain below)
				Other:
the //w	ባለበል/ ከና2 state mn lis • 651-296-63በበ •	• 8(00-657-3864	
ttnc+//ia	•	• %		
ttne://u	•			
Hnc://w	•			Use vour preferred relay service Available in alternative format
	•	Gregor,M	In.55760	
30 O1	• St.,Mc ther compliance conditions	Gregor,M Co	n.55760 mplian	
30 O1	• St.,Mc ther compliance conditions	Gregor,M Co	n.55760 mplian	ce component #3 of 5
0 O1 3a	• St.,Mc 	Gregor,M —— Co pe structur	In.55760 mpliano	ce component #3 of 5

3c. System is non-protective of ground water for other conditions as determined by inspector?	\Box Yes*	No
3d. System not abandoned in accordance with Minn. R. 7080.2500?	Yes*	No
*Yes to 3c or 3d System is failing to protect groundwater.		

Describe verification methods and results:

Property Address: 18157 Driftwood	
-----------------------------------	--

Business Name: Farley Sewer systems

Attached supporting documentation: Not applicable [3 _____

4. Operating permit and nitrogen BMP* — Compliance component #4 of 5 Not applicable

Is the system operated under an Operating Permit?	Yes	No If "yes", A below is required
Is the system required to employ a Nitrogen BMP specified in the system BMP = Best Management Practice(s) specified in the system desig	e	No If "yes", B below is required
If the answer to both questions is "no", this section does not a	need to be complet	ed.
Compliance criteria:		
a. Have the operating permit requirements been met? Yes No		

b. Is the required nitrogen BMP in place and properly functioning? C] Yes □ NO Any "no" answer indicates noncompliancee
 Describe verification methods and results:

Attached supporting documentation: Operating permit (Attach)

https://www.pca.state.mn.us	651-296-6300	•	800-657-3864	٠	Use vour preferred relay service	•	Available in alternative formats
•							of4
18157 Drift	wood St.,McGre	egoi	r,Mn.55760				

5. Soil separation — Compliance component #5 of 5

Date of installation 9/18/1996 (mm/dd/yyyy)	Unknown		
Shoreland/WeIIhead protection/Food lodging?	E Yes 🗌 No beverage	Attached documentation:	supporting
Com liance criteria select one : 5a.For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not senång a food, beverage or lodging establishment:	l Yes No*		
Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock.			



NO DELINQUE	INTTAXES	•	A44067			
ANDTMNSFE	RENTERED OMce of	f the County Recorder Aitki				
This <u>3</u> Day	Aug 2011					
Kulit CC	bunty Auditor	HEREBY CERTIFY THE % RECORDED	THIN INSTRUME ON 8/3/2017 9		D, AND/OR	
linglith	Deputy \$46.00		Depuw	PACKAGE	: 55502	REC FEE:
		Mi	chael T. Moriarty, A	itkin County Reco	rder	
CERTIFICATE.OF REA VALUE (V) FILED (REQUIRED CERTIFICA ESTATE VALUE NO	() NOT					
	(Τ	op 3 inches reserved for re	cording data)			
WARRANTY DEED	Minnesota Uniform	Conveyancing Blanks Inc	dividual(s) to Inc	dividual(s) Fo	rm 10.1.1	(<u>2016)</u> eCRV
number:						
DEED TAX	0	DUE: \$445.50	D	ATE: July 31, 2	017	
				<u> </u>	(montWday/yea	r)
FOR VALUA	BLE CONSIDERA	ATION, Paul	Dzubay,	а	single	person
		(insen nam	e and marital status of ead	ch Grantor)		
						("Grantor"),
hereby conveys and wa	rrants to Doua Lor and Ma	y Lor				
		<u>د</u>	n name of each Grantee)			
						("Grantee"), as
	O tenants in common,	(If more than one Grantee is na	amed above and either	r no box is checked o	or both boxes are	checked,
(Check only one box.)	joint tenants,	this conveyance is made to the	e named Grantees as t	enants in common.)		See
real property in Aitkin attached		County, Minnesota, leg Exhibit A for legal (follows:		
				11237 11237 445.		

D€puiy Check here if all or part of the described real property is Registered (Torrens) O

together with all hereditaments and appurtenances belonging thereto, subject to the following exceptions: Covenants, restrictions, and easements of record, if any.

Page 2 of 2	Page 1 o Minnesota Uniform Conveyancing Blanks Form 10.1.
Check applicable box: a The Seller certifies that the Seller does not know of any wells described real property. A well disclosure certificate accompanies this document been electronically filed. (If electronically filed, insert WDC	or has (signature) Paul Dzubay
I am familiar with the property described in this instrument certify that the status and number of wells on the describ have not changed since the last previously filed well disclo	ped real property
State of Minnesota, County of Aitkin	
nis instrument was acknowledged before me on(r	2017 by Paul Dzubay, a single person
(insen namea	andmarital statusof eachGrantor)
(Stamp)	Christe M. Wike (signature of notarial officer)
ANNETTE M. WILKIE NOTARY PUBLIC-MINNESOTA My Comm. Exp. Jan. 31, 2020	Title (and Rank): My commission expires:(month/day/year)
THIS INSTRUMENT WAS DRAFTED BY: (insert name and auress)	TAX STATEMENTS FOR THE REAL PROPERTY DESCRIBED IN THIS INSTRUMENT SHOULD BE SENT TO: (insert Egal name and resjckntial Of business address of Grantee)
McGregor Title PO Box 309 McGregor, MN 55760	Doua Lor & May Lor 1090 Euclid Street St Paul 55106
-	XHIBII A"

THE NORTHEAST QUARTER OF THE NORTHEAST QUARTER AND THE NORTH 208.18 OF THE EAST 61.3/1' OF THE NORTHWEST QLARTER OF THE NOR^EI'HEAS^TI*

QI ARTER, SECTION 10, TOWNSHIP^z16. RANGE 23, AITKIN COUN'I*Y, MINNESOTA.

Property Address: 18157 Driftwood

Business Name: Farley Sewer systems			Date: 1	0/27/2023		
5b. Non-performance systems built April 1, 1996, or later or for nonperformance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment:	Yes C] No	·* □ □	Soil observation logs completed for the report Two previous verifications of required ve			
Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.*		∟ Not applic	able (No soil treatment area)	separation		
5c. "Experimental", "Other', or "Performance" systems built under pre-	Yes No	,				
2008 Rules; Type IV or V systems built under 2008		A. Bo	ottom of distribution media	101		
Rules 7080. 2350 or 7080.2400		B. Pe	riodicall saturated soil/bedrock	98		
(Intermediate Inspector License required 2, 500 gallons per day; Advanced Inspector		C. S s	stem se aration	36"		
License required > 2, 500 gallons per day)		D. Re	e uired com liance se aration*			
Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.						

Indicate de ths or elevations

*May be reduced up to 15 percent if allowed by Local Ordinance.

*Any "no" answer above indicates the system is failing to protect groundwater,

Describe verification methods and results:

Upgrade requirements: (Minn. Stat. 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.


https://www.nca.state.mn.us • 651-296-6300 • 800-657-3864 • Use your preferred relay service • Available in alternative formats

Jul 09 16 04:15p

p.4

PAGE 84/84

SEWER DESIGN & INSTALLATION



JAROLD R. FARLEY



NO DELINQUE	INTTAXES	•	A44067			
ANDTMNSFE	RENTERED OMce of	f the County Recorder Aitki				
This <u>3</u> Day	Aug 2011					
Kulit CC	bunty Auditor	HEREBY CERTIFY THE % RECORDED	THIN INSTRUME ON 8/3/2017 9		D, AND/OR	
linglith	Deputy \$46.00		Depuw	PACKAGE	: 55502	REC FEE:
		Mi	chael T. Moriarty, A	itkin County Reco	rder	
CERTIFICATE.OF REA VALUE (V) FILED (REQUIRED CERTIFICA ESTATE VALUE NO	() NOT					
	(Τ	op 3 inches reserved for re	cording data)			
WARRANTY DEED	Minnesota Uniform	Conveyancing Blanks Inc	dividual(s) to Inc	dividual(s) Fo	rm 10.1.1	(<u>2016)</u> eCRV
number:						
DEED TAX	0	DUE: \$445.50	D	ATE: July 31, 2	017	
				<u> </u>	(montWday/yea	r)
FOR VALUA	BLE CONSIDERA	ATION, Paul	Dzubay,	а	single	person
		(insen nam	e and marital status of ead	ch Grantor)		
						("Grantor"),
hereby conveys and wa	rrants to Doua Lor and Ma	y Lor				
		<u>د</u>	n name of each Grantee)			
						("Grantee"), as
	O tenants in common,	(If more than one Grantee is na	amed above and either	r no box is checked o	or both boxes are	checked,
(Check only one box.)	joint tenants,	this conveyance is made to the	e named Grantees as t	enants in common.)		See
real property in Aitkin attached		County, Minnesota, leg Exhibit A for legal (follows:		
				11237 11237 445.		

D€puiy Check here if all or part of the described real property is Registered (Torrens) O

together with all hereditaments and appurtenances belonging thereto, subject to the following exceptions: Covenants, restrictions, and easements of record, if any.

Page 2 of 2	Page 1 o Minnesota Uniform Conveyancing Blanks Form 10.1.
Check applicable box: a The Seller certifies that the Seller does not know of any wells described real property. A well disclosure certificate accompanies this document been electronically filed. (If electronically filed, insert WDC	or has (signature) Paul Dzubay
I am familiar with the property described in this instrument certify that the status and number of wells on the describ have not changed since the last previously filed well disclo	ped real property
State of Minnesota, County of Aitkin	
nis instrument was acknowledged before me on(r	2017 by Paul Dzubay, a single person
(insen namea	andmarital statusof eachGrantor)
(Stamp)	Christe M. Wike (signature of notarial officer)
ANNETTE M. WILKIE NOTARY PUBLIC-MINNESOTA My Comm. Exp. Jan. 31, 2020	Title (and Rank): My commission expires:(month/day/year)
THIS INSTRUMENT WAS DRAFTED BY: (insert name and auress)	TAX STATEMENTS FOR THE REAL PROPERTY DESCRIBED IN THIS INSTRUMENT SHOULD BE SENT TO: (insert Egal name and resjckntial Of business address of Grantee)
McGregor Title PO Box 309 McGregor, MN 55760	Doua Lor & May Lor 1090 Euclid Street St Paul 55106
-	XHIBII A"

THE NORTHEAST QUARTER OF THE NORTHEAST QUARTER AND THE NORTH 208.18 OF THE EAST 61.3/1' OF THE NORTHWEST QLARTER OF THE NOR^EI'HEAS^TI*

QI ARTER, SECTION 10, TOWNSHIP^z16. RANGE 23, AITKIN COUN'I*Y, MINNESOTA.



Vacation/Private Home Rental App. # App-2023-001353, UID # 209394 App. Status: Pending Review

> Meeting date: 1/22/24 Date Complete: 12/18/23 60 day: 2/15/24

Contact Information

Aitkin County Planning & Zoning / Environmental Services 307 2nd Street NW, Room 219 Aitkin, MN 56431 Phone: 218-927-7342 Fax: 218-927-4372 Email: aitkinpz@co.aitkin.mn.us

Project Location Search

Property:	Property Location		Legal Description		Property Attributes		Owner Information	Tax Payer Information		
	Parcel Number	Property Address	Township or City Name	Legal Description	Plat Name	Section- Township- Range	Lake Class	Lake Name	Owner Name(s)	Taxpayer Name(s)
	11-1- 090700	43042 Conifer St AITKIN, MN 56431	HAZELTON TWP	LOTS 4 & 5	COOLGALE PARK	S:33 T:45 R:27	GD	MILLE LACS	WAPOLA, ROLAND & CAROL	WAPOLA, ROLAND & CAROL
Driving directions to the property from Aitkin:	Proceed so	uth on US 169 a	approximately 13	s miles, go left (ea	ast) on MN 18 fo	r .3 mile, turn right	(south) o	n Conifer S	Street for .2 mile, hor	ne will be on your righ

Brief Narrative

OneGov

Brief Narrative:	We, Carol and Roland Wapola, own the home at 43042 Conifer St., Aitkin, MN 56431, and are planning to rent it while we are not using it. The home is not homesteaded, since we are already homesteaded in another state (Texas). The rental listings will be handled by Evolve, who have extensive experience locally as well as nationally. AirBnB and VRBO will probably be the primary vehicles. The local contact for issues requiring immediate attention is Sheila Brown. She and her husband, Gabe, handle approximately 35 properties in the area in a similar fashion.
List all current advertising sources: (Be specific and include website links, rental ID #'s, title, etc.) All advertising must be in compliance with the occupancy allowance and all other conditions of the permit. Notify Environmental Services with any changes to the advertising within 30 days.	Our listings will be handled by Evolve.com and will be across multiple platforms in addition to Their own proprietary site. AirBnB and VRBO will be used, and others.
Proposed occupancy of overnight guests:	6
How many rental units will be located on this parcel?	1
Will you be renting for periods of less than one week?	Yes
Quiet hours will begin at:	10 : 00 <u>PM</u>
Quiet hours will end at:	08 : 00 <u>AM</u>

12/26/23, 12:27 PM

OneGov

Floor Plan of Structure

 Please attach a floor plan of the rental unit that includes the following: Label sleeping areas with dimensions Location of egress windows and doors Location of all smoke alarms and carbon monoxide alarms 	File 1: Floor_plan.png
2. How many rooms will be used for sleeping?	3
3. How many carbon monoxide alarms are located in the rental?	3
4. How many smoke detector alarms are located in the rental?	3
5. A fire extinguisher must be placed in an easily accessible location within each rental unit. Where is the fire extinguisher located?	Kitchen, laundry room, garage

Sleeping Area #1

Was this window installed before July 10, 2007?	Yes
Select Window style. (see attached diagram for window style options):	Casement
What is the OPENABLE height of this window:	40 inches
What is the OPENABLE width of this window:	21 inches
What is the distance from the floor to the bottom of this window (finished sill):	36 inches


Sleeping Area #2

Was the largest window in this room installed before July 10, 2007?	Yes
Select window style. (see attached diagram for window style options):	Casement
What is the OPENABLE height of this window?	40 inches
What is the OPENABLE width of this window?	21 inches
What is the distance from the floor to the bottom of this window (finished sill)?	36 inches

Sleeping Area #3

Was the largest window in this room installed before July 10, 2007?	Yes
Select window style. (see attached diagram for window style options):	Casement
What is the OPENABLE height of this window?	40 inches
What is the OPENABLE width of this window?	21 inches
What is the distance form the floor to the bottom of this window (finished sill)?	36 inches

Scaled Site Plan



Emergency Contact Info

Police:	(218) 927 - 2133
Fire:	(218) 927 - 2527
Hospital:	(218) 927 - 2121
Septic Tank Pumper:	(218) 927 - 6175
Where in the rental will the emergency contact information be posted?	Welcome book

Property Information Handbook

Please select all that will be included in your handbook:	Name & contact information for owner and/or caretaker Quiet hours Maximum # of overnight guests Maximum # of non-overnight guests Property rules related to outdoor features List of conditions placed on the approved IUP Notice that all ordinances and IUP conditions will be enforced by the Aitkin County Sheriff's Office and the Aitkin County Environmental Services Department
Where in the rental will your handbook will be located?	On the center island in the kitchen.

Septic Compliance

Attach septic compliance:	Septic_Compliance.pdf	

Water Test Results

Attach Water Test:	File 1: 👆 Water_Test_Results.pdf	

Garbage Disposal Plan

How often will the garbage be collected?	weekly
Please enter the name of the garbage collection service or describe your disposal plan:	Garrison Disposal

Pet Policy

Pet Policy:	We will NOT be allowing pets at our rental.			
-------------	---	--	--	--

Property Deed

|--|--|

Terms

Interior & Exterior Inspection

ed application is accepted by Environmental Services, a staff member will contact you to schedule an interior inspection to verify the information provided in your application of the applicant to have the following in place prior to the inspection:	n. It is
a monoxide alarms installed per MN State Eire Code	
heir designated places and meeting MN State Fire Code	
stalled on the septic system or well	
e property lines	
stalled on the septic system or well	

General Terms

The landowner or authorized agent hereby certifies that to the best of their knowledge the application and supporting documents are a factual representation of the proposed project. The landowner or authorized agent agrees that, in making application, the landowner grants permission to Aitkin County, at reasonable times, to enter the property to determine compliance of the application with applicable Local, County or State Ordinances or Statutes. It is the applicant's responsibility to contact other Local, County or State agencies to ensure the applicant has complied with all relevant Local, County or State Ordinances or Statutes.

Submittal of the above materials does not always constitute a complete application. Other information may be necessary to complete the application based on the type of request and onsite inspection.

I acknowledge that by submitting this application, the application and its attachments are public information.

Invoice #59063 (12/15/2023) Expected Payment Method: Pay Online - Card or ECheck

Charge	Cost	Quantity	Total
Recording Fee added 11/27/2023 5:12 PM This fee is non-refundable if denied.	\$46.00	x 1	\$46.00
Vacation/Private Home Rental added 11/27/2023 5:12 PM This fee is non-refundable if denied.	\$650.00	x 1	\$650.00
Grand Total			
Total			\$696.00
		Payment 12/15/2023	\$696.00
		Due	\$0.00

Approvals

Approval	Signature
Applicant	Roland M. Wapola - 12/18/2023 3:51 PM
	1a4276de5f6e963cbfb7c7c3d3468de0
	b9912275cf52281ab31bf2c1dc351278
#1 Administrative Staff	Connor Plagge - 12/19/2023 10:19 AM
	042825d735abdd7445f88e0377a7b3ae
	be07382755bade72ef415a6cb2e127d4
#2 Planning Commission	


Public Notes


— •		
Text:	To be heard at the January 22nd, 2024 Planning Commission meeting.	
		J
File(s):	·	
	L	

Administrative Staff

This review has been started by:	Connor Plagge V
Zoning District:	Shoreland V
Is the parcel a Lot of Record before 1-21-92 or have alternate sites been identified?	Yes 🗸
Is this an After-The-Fact application?	No 🗸
Current SSTS:	Mound (Type I)
Max Overnight Guests per SSTS:	6

Print View







Septic System Compliance Inspection – Existing System

Date: 8/30/23 Property Owner: Jackels, Bonnie Ordered By: Johnson, Ryan Address: 43042 Conifer Street Aitkin, MN 56431 Property ID#: 11-0-090700 Inspector: Tim Woodrow

A compliance inspection was performed at the above location. Previous evaluations were used to determine the level of seasonal saturated soil. The Soil Treatment Area (Drain field) was also inspected to ensure there was no ponding or leaking. The septic tank was pumped and inspected. This onsite system was found to be **Compliant**.

- Impact On Public Health: System is Compliant
- <u>Tank Integrity:</u> Tank(s) are compliant
- Other Compliance Conditions:
 None
- <u>Soil Separation</u> Soils are compliant
- Operating Permit and Nitrogen BMP
 NA

I have included a copy of the compliance documents for your record. I have also sent a copy to Aitkin County for their records. If you have any questions, please do not hesitate to give us a call.

Thanks! i nom

Tim Woodrow Owner

218-927-6175



DISCLAIMER:

The septic system inspection conducted for this property meets MPCA requirements for existing systems.

We recommend this system to be serviced and evaluated at least every 36 months by a septic professional.

Any additions to the home or increased use of the home may require an increase in system capacity.

- Compliance Requirements evaluated as part of this inspection include the verification that the system tanks do not leak below the designed operating depth, the required separation between the bottom of the subsurface distribution medium and the seasonally saturated soils if applicable, no discharge of septage/effluent to the ground surface or surface water and no imminent safety hazards exist. Timber Lakes Septic Inc does not inspect interior pumps, plumbing, or associated components.
- 2. Certification of this system does not warranty future use beyond the date of inspection. Any system, new or old, can be hydraulically overloaded and discharge to ground surface as a result of increase use(more people in house, faulty plumbing fixtures, change in habits, groundwater infiltration etc), improper maintenance, tree roots, freezing conditions, surface drainage problems, etc. The system can also stop working simply due to its age. The life expectancy of a system is variable and dependent upon the items previously listed. Proper maintenance and water conservation will help contribute to a longer system life.
- 3. A compliance inspection is not meant to be a test or inspection of longevity of the system. A compliance inspection is for the purpose of verifying if the system is protective of public health and safety as well as protecting the ground water at the date and time the inspection was performed. This inspection is not intended to determine if the system was originally designed or installed to past or present MPCA/Local Government Unit Code requirements. This inspection is not intended to determine if the system from buildings as the use of the buildings may have changed since the original design was completed. These changes may include additional bedrooms, occupants, increased use, etc. In addition, this inspection is not intended to determine the quality of the original system design, quality of the construction practices during installation, or quality of materials used.
- 4. Timber Lakes Septic Inc. has not been retained to warranty, guarantee, or certify the proper functioning of the ISTS system for any period of time beyond the date of inspection or into the future. There are numerous factors which may affect the proper operation of a ISTS System and the inability of Timber Lakes Septic to supervise or monitor the use or maintenance of the ISTS System, the Compliance Report shall not be construed as a warranty or guarantee of future system performance.
- 5. By accepting this report, the client understands that Timber Lakes Septic will not be responsible for any monetary damages exceeding the fee for services provided.
- 6. This Report is prepared for the person or rep of the person providing payment for the fees charged.

MINNESOTA POLLUTION CONTROL AGENCY

520 Lafayette Road North St. Paul, MN 55155-4194

Compliance inspection report form

Existing Subsurface Sewage Treatment System (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at https://www.pca.state.mn.us/sites/default/files/wg-wwists4-31a.pdf.

. . Ρ

Property Information	Local tracking	number:	
Parcel ID# or Sec/Twp/Range: <u>11-1-090700</u>	Reason for Inspection	Transfer	
Local regulatory authority info: Aitkin County			
Property address: 43042 Conifer St Aitkin, MN 56431			
Owner/representative: Ryan Johnson-Realtor	·	Owner's phone: 612-865-9391	
Brief system description: 1000/500 septic and lift combo.			

System status

System status on date (mm/dd/yyyy): 8/30/2023

Compliant – Certificate of compliance*

(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)

*Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.

Noncompliant – Notice of noncompliance

Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.

An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.

Reason(s) for noncompliance (check all applicable)

Impact on public health (Compliance component #1) - Imminent threat to public health and safety

Tank integrity (Compliance component #2) – Failing to protect groundwater

Other Compliance Conditions (Compliance component #3) - Imminent threat to public health and safety

Other Compliance Conditions (Compliance component #3) – Failing to protect groundwater

System not abandoned according to Minn. R. 7080.2500 (Compliance component #3) - Failing to protect groundwater

Soil separation (Compliance component #5) - Failing to protect groundwater

Operating permit/monitoring plan requirements (Compliance component #4) - Noncompliant - local ordinance applies

Comments or recommendations

Certification

I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage

By typing my name below, I certify the above statements to be true and correct, to the best of my knowledge, and that this information can be used for the purpose of processing this form.

Business name: Timber Lakes Septic Service		Certification number: C7644
Inspector signature:	Tim Woodrowl	License number: L455
	(This document has been electronically signed)	Phone: 218-927-6175

Necessary or locally required supporting documentation (must be attached)

Soil observation logs	System/As-Built	Locally required forms	Tank Integrity Assessment	Operating Permit
Other information (list):				

1. Impact on public health – Compliance component #1 of 5

Compliance criteria:		Attached supporting documentation:
System discharges sewage to the ground surface	🗋 Yes* 🛛 No	Other: Not applicable
System discharges sewage to drain tile or surface waters.	🗌 Yes* 🛛 No	_
System causes sewage backup into dwelling or establishment.	🗋 Yes* 🖾 No	
Any "yes" answer above indicates imminent threat to public health an	<i>JF</i>	-

Describe verification methods and results:

2. Tank integrity – Compliance component #2 of 5

Compliance criteria:		Attached supporting d	locumentation:
System consists of a seepage pit, cesspool, drywell, leaching pit, or other pit?	☐ Yes* ⊠ No	☐ Empty tank(s) viewed b Name of maintenance I	
Sewage tank(s) leak below their ☐ Yes* ⊠ No designed operating depth?		License number of maintenance business: Date of maintenance:	
		🛛 Existing tank integrity a	assessment (Attach)
If yes, which sewage tank(s) leaks:		Date of maintenance (mm/dd/yyyy):	8/28/2023 (must be within three years)
Any "yes" answer above indicates the system is failing to protect groundwater.		(See form instructions to ensure assessment complies wit Minn. R. 7082.0700 subp. 4 B (1))	
		☐ Tank is Noncompliant (pumping not necessary – explain below	
		Other:	
Describe verification methods and	d results:		

٠

٠

Business Name: ______ Timber Lakes Septic Service

3. Other compliance conditions – Compliance component #3 of 5

3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsecured? □ Yes* ⊠ No □ Unknown 3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety? □ Yes* ⊠ "Yes to 3a or 3b - System is an imminent threat to public health and safety. 3c. System is non-protective of ground water for other conditions as determined by inspector? □ Yes* ⊠ 3d. System not abandoned in accordance with Minn. R. 7080.2500? □ Yes* ⊠ "Yes to 3c or 3d - System is failing to protect groundwater. Describe verification methods and results: Attached supporting documentation: □ Not applicable □ 4. Operating permit and nitrogen BMP* – Compliance component #4 of 5 ⊠ Not Is the system operated under an Operating Permit? □ Yes □ No If "yes", A bell Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No If "yes", B bell BMP = Best Management Practice(s) specified in the system design	No
 □ Yes* ⊠ No □ Unknown 3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety? □ Yes* ⊠ "Yes to 3a or 3b - System is an imminent threat to public health and safety. 3c. System is non-protective of ground water for other conditions as determined by inspector? □ Yes* ⊠ 3d. System not abandoned in accordance with Minn. R. 7080.2500? □ Yes* ☑ *Yes to 3c or 3d - System is failing to protect groundwater. Describe verification methods and results: Attached supporting documentation: □ Not applicable □ 4. Operating permit and nitrogen BMP* – Compliance component #4 of 5 ⊠ Not is the system operated under an Operating Permit? □ Yes □ No If "yes", A bell is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No If "yes", B bell	No
 Yes to 3a or 3b - System is an imminent threat to public health and safety. 3c. System is non-protective of ground water for other conditions as determined by inspector? □ Yes ☑ 3d. System not abandoned in accordance with Minn. R. 7080.2500? □ Yes* ☑ *Yes to 3c or 3d - System is failing to protect groundwater. Describe verification methods and results: Attached supporting documentation: □ Not applicable □ 4. Operating permit and nitrogen BMP* – Compliance component #4 of 5 ☑ Not applicable Is the system operated under an Operating Permit? □ Yes □ No If "yes", A bell is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No If "yes", B bell 	No
 Yes to 3a or 3b - System is an imminent threat to public health and safety. 3c. System is non-protective of ground water for other conditions as determined by inspector? □ Yes ☑ 3d. System not abandoned in accordance with Minn. R. 7080.2500? □ Yes* ☑ *Yes to 3c or 3d - System is failing to protect groundwater. Describe verification methods and results: Attached supporting documentation: □ Not applicable □ 4. Operating permit and nitrogen BMP* – Compliance component #4 of 5 ☑ Not applicable Is the system operated under an Operating Permit? □ Yes □ No If "yes", A bell is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No If "yes", B bell 	No
3d. System not abandoned in accordance with Minn. R. 7080.2500? □ Yes* ⊠ *Yes to 3c or 3d - System is failing to protect groundwater. Describe verification methods and results: Describe verification methods and results:	
*Yes to 3c or 3d - System is failing to protect groundwater. Describe verification methods and results: Attached supporting documentation: Not applicable Is the system operated under an Operating Permit? Yes Not Is the system required to employ a Nitrogen BMP specified in the system design? Yes No If "yes", A bel	No
Describe verification methods and results: Attached supporting documentation: Not applicable . Operating permit and nitrogen BMP* – Compliance component #4 of 5 Not Is the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? Yes No Is the system required to employ a Nitrogen BMP specified in the system design?	
Attached supporting documentation: Not applicable •. Operating permit and nitrogen BMP* – Compliance component #4 of 5 Not applicable Is the system operated under an Operating Permit? Yes Not if "yes", A beled is the system required to employ a Nitrogen BMP specified in the system design?	
Operating permit and nitrogen BMP* – Compliance component #4 of 5 ⊠ Not and a system operated under an Operating Permit? Source Structure Structur	
Operating permit and nitrogen BMP* – Compliance component #4 of 5 ⊠ Not and a system operated under an Operating Permit? Source Structure Structur	
Operating permit and nitrogen BMP* – Compliance component #4 of 5 ⊠ Not Is the system operated under an Operating Permit? □ Yes □ No If "yes", A bel Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No If "yes", B bel	
Operating permit and nitrogen BMP* – Compliance component #4 of 5 Not a ls the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? Yes No If "yes", B bell is the system required to employ a Nitrogen BMP specified in the system design?	
Operating permit and nitrogen BMP* – Compliance component #4 of 5 ⊠ Not and a system operated under an Operating Permit? Source Structure Structur	
Operating permit and nitrogen BMP* – Compliance component #4 of 5 ⊠ Not Is the system operated under an Operating Permit? □ Yes □ No If "yes", A bel Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No If "yes", B bel	
Operating permit and nitrogen BMP* – Compliance component #4 of 5 ⊠ Not and the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No If "yes", B bell	
Operating permit and nitrogen BMP* – Compliance component #4 of 5 ⊠ Not and the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No If "yes", B bell	
Operating permit and nitrogen BMP* – Compliance component #4 of 5 ⊠ Not and a system operated under an Operating Permit? Source Section 1 Stress Section 2 Stress Sect	
Operating permit and nitrogen BMP* – Compliance component #4 of 5 ⊠ Not and a system operated under an Operating Permit? Source Section 1 Stress Section 2 Stress Sect	
Operating permit and nitrogen BMP* – Compliance component #4 of 5 ⊠ Not Is the system operated under an Operating Permit? □ Yes □ No If "yes", A bel Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No If "yes", B bel	
Operating permit and nitrogen BMP* – Compliance component #4 of 5 Not a ls the system operated under an Operating Permit? Is the system required to employ a Nitrogen BMP specified in the system design? Yes No If "yes", B bell is the system required to employ a Nitrogen BMP specified in the system design?	
Is the system operated under an Operating Permit? □ Yes □ No If "yes", A bel Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No If "yes", B bel	
Is the system operated under an Operating Permit? □ Yes □ No If "yes", A bel Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No If "yes", B bel	
Is the system operated under an Operating Permit? □ Yes □ No If "yes", A bel Is the system required to employ a Nitrogen BMP specified in the system design? □ Yes □ No If "yes", B bel	applicable
Is the system required to employ a Nitrogen BMP specified in the system design? Yes No If "yes", B bel	
	-
BMP = Best Management Practice(s) specified in the system design	ow is requir
If the answer to both questions is "no", this section does not need to be completed.	
Compliance criteria:	
a. Have the operating permit requirements been met?	
b. Is the required nitrogen BMP in place and properly functioning? 🔲 Yes 🔲 No	
Any "no" answer indicates noncompliance.	
Describe verification methods and results:	

Attached supporting documentation: Operating permit (Attach)

Business Name: Timber Lakes Septic Service

5. Soil separation – Compliance component #5 of 5

Date of installation 7/9/2001 (mm/dd/yyyy)	Unknown	
 Shoreland/Wellhead protection/Food beverage lodging? Compliance criteria (select one): 5a. For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment: Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock. 5b. Non-performance systems built April 1, 1996, or later or for non- performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment: Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.* 	⊠ Yes □ No*	Attached supporting documentation: Soil observation logs completed for the report Two previous verifications of required vertical separation Not applicable (No soil treatment area) Indicate depths or elevations A. Bottom of distribution media B. Periodically saturated soil/bedrock C. System separation D. Required compliance separation* *May be reduced up to 15 percent if allowed by Local Ordinance.
 5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License required ≤ 2,500 gallons per day; Advanced Inspector License required > 2,500 gallons per day) Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock. 		

*Any "no" answer above indicates the system is failing to protect groundwater.

Describe verification methods and results:

Upgrade requirements: (*Minn. Stat.* § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.

MINNESOTA POLLUTION CONTROL AGENCY

Sewage tank integrity assessment form

520 Lafayette Road North St. Paul, MN 55155-4194

Subsurface Sewage **Treatment Systems (SSTS) Program**

Doc Type: Compliance and Enforcement

Purpose: This form may be used to certify the compliance status of the sewage tank components of the SSTS. This form is not a complete SSTS inspection report, only a tank integrity assessment, and may only certify sewage tank compliance status when entirely completed and signed by a qualified professional. SSTS compliance inspection report forms can be found at: https://www.pca.state.mn.us/water/inspections.

Instructions: This form may be completed, and signed, by a Designated Certified Individual (DCI) of a licensed SSTS inspection maintenance, installation, or service provider business who personally conducts the necessary procedures to assess the compliance status of each sewage tank in the system. Only a licensed maintenance business is authorized to pump the tank for assessment. A copy of this information should be submitted to the system owner and be maintained by the licensed SSTS business for a period of five (5) years from the assessment date.

When this form is signed by a qualified certified professional, it becomes necessary supporting documentation to an Existing System Compliance Inspection Report: Compliance inspection form - Existing system (wg-wwists4-31b). This form can be found on the MPCA website at https://www.pca.state.mn.us/water/inspections.

The information and certified statement on this form is required when existing septic tank compliance status is determined by an individual other than the SSTS Inspector that submits an inspection report. This form represents a third party assessment of SSTS component compliance and is allowable under Minn. R. 7082.0700, subp. 4(B)(1). This form is valid for a period of three years beyond the signature date on this form unless a new evaluation is requested by the owner or owner's agent or is required according to local regulations. Additional Administrative Rule references for this activity can be found at Minn. R. 7082.0700, subp. 4(B),(C), and (D) and; Minn. R. 7083.0730(C).

Owner information

Owner/Representative Jackels, Bonnie

Property address: 43042 Conifer St, Aitkin, MN 56431

Local Regulatory Authority: Aitkin County

Parcel ID: 11-1-090700

System status

System status on date (mm/dd/yyyy):	8/28/2023	
Certificate of sewage tar	nk compliance	Notice of sewage tank non-compliance
Compliance criteria:		

The SSTS has a seepage pit, cesspool, drywell, leaching pit, or other pit - "Failure to Protect □ Yes* ⊠ No Groundwater." The SSTS has a sewage tank that leaks below the designed operating depth - "Failure to Protect 🗌 Yes* 🛛 No Groundwater." The SSTS presents a threat to public safety by reason of structurally unsound (damaged, cracked, 🗌 Yes* 🛛 No

or weak) maintenance hole cover(s) or lids or any other unsafe condition - "Imminent Threat to Public Health or Safety."

Any "yes" answer above indicates sewage tank non-compliance.

Company information

Designated Certified Individual (DCI) information


Company name:	Timber Lakes Septic Service Inc	Print name: Craig Perlberg	
Business license	number: L455	Certification number: C6023	

I personally conducted the work described above as a Designated Certified Individual of a Minnesota-licensed SSTS inspection, maintenance, installation, or service provider Business. I personally conducted the necessary procedures to assess the compliance status of each sewage tank in this SSTS.

By typing/signing my name below, I certify the above statements to be true and correct, to the best of my knowledge, and that this information can be used for the purpose of processing this form.

Designated Certified Individual's signature:	Craig Perlberg
•	(This document has been electronically signed.)

Date (mm/dd/yyyy):_**8/28/2023**



FIELD EVALUATION SHEET

*

.

PRELIMINARY EVALUA PROPERTY OWNER: ADDRESS: <u>P.o.</u> (3.0) LEGAL DESCRIPTION: PIN# //-/- 090700///- FIRE#LAKE/RI	Lots 4 and	STATE ZIP: A	WP NAME HOZELTON CE CLASS & OHWL FT.
DISTURBED AREAS COMPACTED AREAS FLOODING RUN ON POTENTIAL SLOPE % DIRECTION OF SLOPE LANDSCAPE POSITION VEGETATION TYPES	YES NO VE YES NO VE YES NO VE YES NO VE YES NO VE YES NO VE MorTh No Side Slope S Hardwoods H	REA #2 S NO L S NO L S NO L S NO L S NO L 3 MO L S NO L S SLOPE	REFERENCE BM ELEV. /000 FT REFERENCE BM DESCRIPTION Water Level of Mulle Lacs Lake ON 4/14/01
	SITE EVALUATOR SIG	TOM OF ROCK	BED: #1//0.2 FT., #2///.0 FT. /.27 EPHONER(2/8) 678-2/4/ DATE
	SOIL BORING LO	38 ON REVER S	
		J . 20	APPROVED ONSITE INSPECTION <u>A</u> NO ONSITE INSPECTION SIGN <u>RPC</u> DATE <u>47000</u>

SOILS CHARTS FOR BOTH PROPOSED AND ALTERNATE SITES

1 (PROPOSED) SOILS DATA

DEPTH TEXTURE MONSELL (NCRES) COLOR 0-8 TOP SOIL 10YR 3/1 8-14 SONDY LODM 7. SYR 5/6 14- MOTTLed-EL. 107,0

1 (ALTERNATE) SOILS DATA

DEPTH			
(ANCHER)		COLON	
1:0-12	Top Soil	10 YR 2/1	-
		an TYR 4/	6
24 - 1	rottled	EL. 107,0	1
	*		
			1
			I

2 (PROPOSED) SOILS DATA

DEPTN PERIOR JUDGET (NCRES) COLOR 0-8 Top Soil 104R 3/1 8-14 SDNAY LOOM J.SYR 5/6 14-MOTTLED EL, 106.5

2 (ALTERNATE) SOILS DATA

0-10 Top Soil 104R 3/, 10-15 Sandy Lown 7.54R 5/6 15-MOTTLed EL.-107.2


Additional soil Borings May be regulad

NAMELES MOSER	PERMIT # 222
PARCEL # <u>#1/-/-6907000.30</u>	0 TWP <u>HAZEL ZON</u> PERMIT #_ <u>277</u> SECT
CHECK THE FOLLOWING PRIOR	
	NAME OF SITE EVALUATOR
	NAME OF DESIGNER
	NAME OF INSTALLER
LOT OF RECORD BEFORE	1-21-92 (SL) OR 1-10-95 (NSL), IF NO, ALT.S
OUE PLAN WITH SETBAC	K DISTANCES AND DIMENSIONS
ARE ISTS SITES PROTECT	ED FROM DAMAGE? IF NOT, WHEN
	ERC TESTS SOIL BORINGS, 2
	TRENCH DESIGN SHEE OTHER OR PERFORMAN SHEET PUMP CALCULATION S
PRESSURE DISTRIBUTION	
WATER USE CALCULATIO	NS PUIVIP CALCULATION S
GARBAGE DISPOSA	ALHOT TUB
EASEMENTS ON LC	T, IS ROAD PUBLIC OR PRIVATE (SEE DE
NATUARL LANDSCA	PE PROTECTION PLAN
CTAVINO. DEBLORIOS	
BUILDING SETRACKS, DOAD	DRAINFIELD, BORINGS, WI , SIDE, REAR, BLUFF, LAKE/RI
SETBACKS (MEASURE DISTANCE)	
SETBACKS (MEASURE DISTANCE) FLOOD PLAIN WETLANDS LAKE, RIVER, PROTECTED WATER ROAD RIGHT OF WAY BLUFF SIDE LOT LINE REAR LOT LINE HOUSE OR OTHER STRUCTURE WELL EASEMENTS NEIGHBORING WELL(S) TO ISTS	DRAINFIELD HOUSE YES/NO YES/NO YES/NØ YES/NO
SETBACKS (MEASURE DISTANCE) FLOOD PLAIN WETLANDS LAKE, RIVER, PROTECTED WATER ROAD RIGHT OF WAY BLUFF SIDE LOT LINE REAR LOT LINE HOUSE OR OTHER STRUCTURE WELL EASEMENTS NEIGHBORING WELL(S) TO ISTS DRAINFIELD AREA DISTURBED	$S = \frac{DRAINFIELD}{YES/NO} + OUSEYES/NO} YES/NOYES/NOYES/NOYES/NOYES/NOYES/NOYES/NOYES/NOYES/NONONONONONONONONONONONONON$
SETBACKS (MEASURE DISTANCE) FLOOD PLAIN WETLANDS LAKE, RIVER, PROTECTED WATER ROAD RIGHT OF WAY BLUFF SIDE LOT LINE REAR LOT LINE HOUSE OR OTHER STRUCTURE WELL EASEMENTS NEIGHBORING WELL(S) TO ISTS DRAINFIELD AREA DISTURBED 	S $ \frac{DRAINFIELD}{YES/NO} + OUSE YES/NO YES/NO YES/NO YES/NO YES/NO YES/NO 100'+ 15' 0L-AM/SINC 30' NO 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 30' NO 10'+ 3$
SETBACKS (MEASURE DISTANCE) FLOOD PLAIN WETLANDS LAKE, RIVER, PROTECTED WATER ROAD RIGHT OF WAY BLUFF SIDE LOT LINE REAR LOT LINE HOUSE OR OTHER STRUCTURE WELL EASEMENTS NEIGHBORING WELL(S) TO ISTS DRAINFIELD AREA DISTURBED 	S DRAINFIELD YES/NO NO NO NO NO NO NO NO
SETBACKS (MEASURE DISTANCE) FLOOD PLAIN WETLANDS LAKE, RIVER, PROTECTED WATER ROAD RIGHT OF WAY BLUFF SIDE LOT LINE HOUSE OR OTHER STRUCTURE WELL EASEMENTS NEIGHBORING WELL(S) TO ISTS DRAINFIELD AREA DISTURBED 	S $ \frac{DRAINFIELD}{YES/NO} + OUSE YES/NO YES/NO YES/NO YES/NO YES/NO YES/NO 100'+ 15' 0L-AM/SINC 30' NO 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 30' NO 10'+ 3$
SETBACKS (MEASURE DISTANCE) FLOOD PLAIN WETLANDS LAKE, RIVER, PROTECTED WATER ROAD RIGHT OF WAY BLUFF SIDE LOT LINE HOUSE OR OTHER STRUCTURE WELL EASEMENTS NEIGHBORING WELL(S) TO ISTS DRAINFIELD AREA DISTURBED 	S $ \frac{DRAINFIELD}{YES/NO} + OUSE YES/NO YES/NO YES/NO YES/NO YES/NO YES/NO 100'+ 15' 0L-AM/SINC 30' NO 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 30' NO 10'+ 3$
SETBACKS (MEASURE DISTANCE) FLOOD PLAIN WETLANDS LAKE, RIVER, PROTECTED WATER ROAD RIGHT OF WAY BLUFF SIDE LOT LINE REAR LOT LINE HOUSE OR OTHER STRUCTURE WELL EASEMENTS NEIGHBORING WELL(S) TO ISTS DRAINFIELD AREA DISTURBED 	S $ \frac{DRAINFIELD}{YES/NO} + OUSE YES/NO YES/NO YES/NO YES/NO YES/NO YES/NO 100'+ 15' 0L-AM/SINC 30' NO 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 10' 10'+ 30' NO 10'+ 3$

*


SOIL BORING LOG #1 DEPTH TEXTURE	COLOR	SOIL BORIN DEPTH		COLOR
D-71 TOP SO.Z				
8" - 16" SANDY LOAM				
8" - 16 " SANOY COM MOTTLES @ 14 4				
			· ·	

IDENTIFY LOCATIONS OF: (Borings, neighboring structures, wells, drainfields, drainage patterns, or other features that may impact the site).




26 07 10:30 a	Bartel Bob		218 829 6	5742 p.1
	11-1-090	700	2/25/02	Water/Wastewater-15754.31
S			n Form for Brisling resiment Systems	Minnesota Pollution Control Agency
Completion of thi to local ordinance	's form fulfills the minimal requirem as for other regularments or inform	ents of Mino. Si Blion, especiali	at. § 115.55 (2001) and Minneso For compliance requirements for	ta R. ch. 7060 (1999). Please raier bedroom additions.
General:				
Date of Inspe	tion: 9.20-07 Reason	forinspecti	= Salling	
	er(s) William Man		· · · · ·	shone (
Person receives	tino i nsoscijan			abone ()
Site Address	43048 conter 3	17	any Mitkin	Zip Code <u>376431</u>
Fire No./ Parce	a ma. 11-1-090760	Country /	1/6: Townest	ip Hozelton
Legal Descript	in 10+4.5		45 27	•
Local Regulate	my Automating Aithin			•
	onstructed <u>di</u>	Sisten	in Shaneland Area: A no) System in Wellhead
	a: yas / D System serving:	a 1-20% Reens	ed facility: yes/ng Local P	≥===≥ ₽ (if anv)
Frotection: Are Systems bu Shoreland or	a: yes (10) System serving : It prior to April 1, 1996 and n Wellhead Protection Area or S everage or Lodging Establishme	ist located in Erving a Food,	Systems located in Shor Areas or Serving a Fo Establishment; or	elanti or Wellhand Protection od, Beverage or Lodging systems Built after
Frotection: Are Systems bu Shoreland or	It prior to April 1, 1996 and m Wellhead Protection Area or S	ist located in Erving a Food,	Systems located in Shor Areas or Serving a Fo Establishment; or	eland or Wellhead Protection
Frotection: Are Systems bu Shoreland or B Is the sestem <u>sefety? (a yes</u> - Discharge of se	It prior to April 1, 1996 and r Wellhead Protection Area or S everage or Lodging Establishme answar is an ITPHS system) wage to the ground surface?	st located in erving a Food, ant lic heats or YES ND	Systems located in Shor Areas or Serving a Fo Establishment, or March Is the sustant an institut or safishing (a yes answer i - Escharge of sewage to the g	eland or Wellhead Protection od, Beverage or Lodging systems Built after 31, 1996 Stan JTPHS system) nound surface? YES (197
Frotection Are Systems bu Shoreland or B Is the system <u>sefety?</u> (3 yes - Discharge of se - Discharge of se	It prior to April 1, 1996 and r Wellhead Protection Area or S everage or Lodging Establishme answar is an ITPHS system) wage to the ground surface? wage to chaintile or surface?	Not located in ierving a Food, ant lic health or Yes NO i? Yes NO	Systems located in Shor Areas or Serving a Fo Establishment, or March Is the sustant an implice or safety? (a yes answer i - Discharge of sevage to the g - Discharge of sevage to drein	eland or Wellhead Protection od, Beverage or Lodging systems Built after 31, 1996 Stifffrent to public health 5 an JTPHS system) nound surface? YES
Frotection Are Systems bu Shoreland or B Is the sastern <u>sefety? (a yes</u> - Discharge of se - Discharge of se - Sewage backap - Situation with M	It prior to April 1, 1996 and re Wellhead Protection Area or S everage or Lodging Establishms answar is an ITPHS system) wage to the ground surface? wage to drainlike or sufface? wage to drainlike or sufface? wage to drainlike or sufface? and dwaling?	st located in erving a Food, ant lic heats or YES ND	Systems located in Sher Areas or Serving a Fo Establishment, or March Is the sustant, an implies or safety? (a yes answer i - Discharge of sevage to drein - Discharge of sevage to drein - Sewage backup into dwelling - Situation with the pater tal in	eland or Wellhead Protection od, Beverage or Lodging r systems Built after 31, 1996 Stit Arcent in public health 5 an JTPHS system) pound surface? YES 2 YES 2 YES 2 YES 2 Statements and
Frotection Are Systems bu Shoreland or B Is the system <u>setety?</u> (3 yes - Discharge of se - Discharge of se - Discharge of se - Situation with t adversely impo	It prior to April 1, 1996 and m Wellhead Protection Area or S everage or Lodging Establishme answar is an ITPHS system) wage to the ground surface? wage to draintile or surface waters into dwelling?	Not located in ierving a Food, ant lic health or Yes NO Yes NO Yes NO	Systems located in Shor Areas or Serving a Fo Establishment, or March Is the sustant, an implies or safety? (a yes answer i - Discharge of sevage to drein - Discharge of sevage to drein - Sewage backup into dwelling - Situation with the pater tal in adversely impact or threaten	eland or Wellhead Protection od, Beverage or Lodging rsystems Built after 31, 1995 Ent. Threat to public health is an JTPH'S system) acount surface? YES the or surface waters? YES ? YES insmediately and a public health or
Frotection Are Systems bu Shoreland or B Is the sastern safety? (2 yes Otscharge of se Otscharge of se Otscharge of se Sevege backup Situation with H adversely impe safety?	It prior to April 1, 1996 and re Wellhead Protection Area or S everage or Lodging Establishms answar is an IIPHS system) wage to the ground surface? wage to chaintile or sufface? wage to chaintile or sufface? in dwaling? to potential to incrediately and act or threaten public health or	Not located in lerving a Food, ant lic health or YES NO YES NO YES NO YES NO	Systems located in Shor Areas or Serving a Fo Establishment, or March Is the session an immine or setting of sevage to drain - Discharge of sevage to drain - Sevage backup into dwelling - Situation with the pater tial is adversely impact or threater safety?	elanci or Wellhead Protection od, Beverage or Lodging systems Built after 31, 1996 <u>BECTOREST to public health</u> 5 an JTPH'S system) nound surface? YES 2 2 2 YES 2 2 NES 2 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3 3
Protection Are Systems but Shoreland or Br Is the sastern <u>safety? (2 yes</u> - Discharge of se - Discharge of se - Situation with the adversely impor- safety? Is the system	It prior to April 1, 1996 and re Wellhead Protection Area or S everage or Lodging Establishme answar is an ITPHS system) wage to the ground surface? wage to chaintile or sufface? wage to chaintile or sufface waters into dweling? To potential to immediately and act or threaten public heads or <u>Selfcool</u> (a yes answar is a fail	Not located in kerving a Food, ant Not head to or Yes NO YES NO YES NO YES NO	Systems located in Sher Areas or Serving a Fo Establishment, or March In the sestern an immine Or setting of sevage to the Obstance of sevage to their Several backup into dwelling - Statistics with the potential in advessely impact or threater safety? Is the system felling? (a	eland or Wellhead Protection od, Beverage or Lodging systems Built after 31, 1996 EXTINEED to public health 5 an JTPH'S system) nound surface waters? YES YES associately and a public health or YES (M) yes answer is a feiling system)
Protection Are Systems but Shoreland or B is the sastern <u>safety?</u> (a yes - Dictarge of se - Dictarge of se - Dictarge of se - Sibation with the advecely imper- safety? Is the system - Less than TU/D	It prior to April 1, 1996 and re Wellhead Protection Area or S everage or Lodging Establishms answar is an IIPHS system) wage to the ground surface? wage to chaintile or sufface? wage to chaintile or sufface? in dwaling? to potential to incrediately and act or threaten public health or	Not located in kerving a Food, ant Not head to or Yes NO YES NO YES NO YES NO	Systems located in Shor Areas or Serving a Fo Establishment, or March Is the session an immine or setting of sevage to drain - Discharge of sevage to drain - Sevage backup into dwelling - Situation with the pater tial is adversely impact or threater safety?	eland or Wellhead Protection od, Beverage or Lodging systems Built after 31, 1996 EXTREME to public health 5 an JTPH'S system) nound surface? YES Bile or surface waters? YES ? YES immediately and a public besith or YES (M) yes answer is a failing system) tical separation between
Protection Are Systems but Shoreland or B Is the sustem Select? (a yes Otscharge of se Otscharge of se Otscharge of se Situation with the adversely imper- safety? Is the system Less than TU70 System bottom	It prior to April 1, 1996 and re Wellhead Protection Area or S everage or Lodging Establishms answar is an IIPHS system) wage to drainfile or sufface? wage to drainfile or sufface? wage to drainfile or sufface? in dwelling? to potential to incrediately and act or threaten public health or <u>faitEros?</u> (a yes answer is a fait feat of vertical supercision between	Not located in lerving a Food, ant lic health or YES NO YES NO YES NO YES NO	Systems located in Shor Areas or Serving a Fo Establishment, or March Is the sester an implies or setting of sevage to the Discharge of sevage to drain - Sevage backup into dweling - Situation with the pair tial is adversely impact or threater safety? Is the sustem failing? (a - Less then THREE fact of vert	elanci or Wellhead Protection od, Beverage or Lodging resistants Built after 31, 1996 Stantast in public health is an JTPH'S system) nound surface? YES insmediately and a public besith or YES MAN YES EASwer is a felling system) ical separation between of soil or bedruck? YES
Protection Are Systems bu Shoreland or B Shoreland or B Is the sheatern safety? (2 yes Olicharge of se Olicharge of se Olicharge of se Stration with the adversely imper- safety? Is the system - Less than TU/D system bottom - A scepage pit, c	It prior to April 1, 1996 and re Wellhead Protection Area or S everage or Lodging Establishme answar is an IIPHS system) wage to drainfile or sufface? wage to drainfile or sufface? wage to drainfile or sufface? wage to drainfile or sufface? and westing? to potential to incrediately and act or threaten public hestile or <u>failEcol?</u> (a yes answer is a fail feat of vertical separation between and seturated soll or bedrock? esspeed, drywell, or leaching pit?	Not located in lerving a Food, ant NES NO YES NO YES NO YES NO YES NO YES NO	Systems located in Shor Areas or Serving a Fo Establishment, or March Is the sustem an immine or setting of sevage to their - Discharge of sevage to their - Sevage backup into dwelling - Less than THREE fact of vert system bottom and saturate	elanci or Wellhead Protection od, Beverage or Lodging rsystems Built after 31, 1996 Statute States (States) pound surface? YES tile or surface waters? YES insmediately and a public besith or YES (S) YES answer is a failing system) ical separation between of soil or bedruck? YES (S)
Protection Are Systems bu Shoreland or B Is the sustem <u>sefery?</u> (a yes - Discharge of se - Discharge of se - Discharge of se - Discharge of se - Stanton with the adversely imper- safety? Is the system - A scepage pit, c Is the system	It prior to April 1, 1996 and re Wellhead Protection Area or S everage or Lodging Establisher answar is an IIPH'S system) wage to the ground surface? wage to the ground surface? wage to the drainille or surface values into dwelling? The potential to Insuediately and act or threaten public heading of feet of vertical separation between and selurated soft or between	Not located in kerving a Food, ant NES NO YES NO YES NO YES NO YES NO YES NO YES NO YES NO YES NO	Systems located in Shor Areas or Serving a Fo Establishment, or March Is the session an insting or set by? (a yes assure i - Lischarge of sevage to thein - Savage backup into dweling - Less then THREE feet of vert system bottom and savate - A seepage pit, caspool, dryw Te the system regulated	eland or Wellhead Protection od, Beverage or Lodging rsystems Built after 31, 1996 Schtreet is public health is an JTPH'S system) nound surface? YES is a surface waters? YES is a surface waters? YES a surface waters?
Protection Are Systems bu Shoreland or B Is the system Scharge of se Dicharge of se Dicharge of se Dicharge of se Station with H advessly imposed Sibration with H advessly impo safety? <u>Is the system</u> - Less than TU7D system bottom - A scepage pit, c <u>Is the system</u> operating permit	It prior to April 1, 1996 and re Wellhead Protection Area or S everage or Lodging Establisher answar is an IIPH'S system) wage to the ground surface? wage to drainille or surface values into dwelling? The potential to Insuediately and act or threaten public headin or <u>Selferst?</u> (a yes answer is a fak feet of vertical separation between and selurated soll or betweek? asspeed, drywell, or leading pit?	Not located in kerving a Food, ant NES NO YES NO YES NO YES NO YES NO YES NO YES NO	Systems located in Shar Areas or Serving a Fo Establishment, or March In the sestern an immine or setting of sevage to the g - Discharge of sevage to the g - Discharge of sevage to the g - Discharge of sevage to the g - Severate backup into dwelling - Less than THREE fact of vert system bottom and saturate - A seepage pit, cesspool, dryw Is the system regulated operating permit? (if no, go	eland or Wellhead Protection od, Beverage or Lodging rsystems Built after 31, 1996 Schtreet is public health is an JTPH'S system) nound surface? YES is a surface waters? YES is a surface waters? YES a surface waters?
Protection Are Systems but Shoreland or B Is the sastern safety? (a yes - Discharge of se - Discharge of se - Discharge of se - Sibation with the advessely imper- safety? Is the system - Less than TU/D system bottom - A scepage pit, c Is the system operating permit <i>If</i> yes,	It prior to April 1, 1996 and re Wellhead Protection Area or S everage or Lodging Establishms answar is an ITPHS system) wage to the ground surface? wage to daintile or sufface? wage to daintile or sufface? and dealing? to premise to immediately and act or threaten public health or <u>failEnce?</u> (a yes answer is a fail feet of vertical superclan between and seturated soll or bedrack? esspeed, drywell, or leaching pit? <u>com-compliants?</u> regulated under a monitoring pit? (if no, go to page 2)	Not located in kerving a Food, ant NES NO YES NO YES NO YES NO YES NO YES NO YES NO YES NO YES NO	Systems located in Shor Areas or Serving a Fo Establishment, or March Is the session an insting or set by? (a yes assure i - Lischarge of sevage to thein - Savage backup into dweling - Less then THREE feet of vert system bottom and savate - A seepage pit, caspool, dryw Te the system regulated	eland or Wellhead Protection od, Beverage or Lodging rsystems Built after 31, 1996 EXAMPLES problec health is an JTPH'S system) nound surface? YES tills or surface waters? YES ? YES insmediately and a public basisth or YES MAN yes answer is a felling system) ical separation between of soil or bedrock? YES well, or leaching pil? YES ieart? I under a monitoring plan or to page 2) YES MAN
Protection Are Systems but Shoreland or B Is the sustem Selection with the adversely impa- safety? Is the system - Less than TU7D system bottom - A scapage pit, c Is the system operating permit If yes, - Has the require	It prior to April 1, 1996 and re Wellhead Protection Area or S everage or Lodging Establisher answar is an IIPH'S system) wage to the ground surface? wage to the ground surface? wage to the drainille or surface values into dwelling? The potential to Insuediately and act or threaten public heading of feet of vertical separation between and selurated soft or between	Not located in lerving a Food, ant VES NO YES NO YES NO YES NO YES NO YES NO YES NO YES NO YES NO	Systems located in Shor Areas or Serving a Fo Establishment, or March Is the system an implies or setting of sevage to their - Discharge of sevage to their - Sevage backup into dwelling - Less than TMREE fact of vert system bottom and saturate - A seepage pit, cesspool, dryw Is the system regulated operating permit? (If no, go i Wyes,	eland or Wellhead Protection od, Beverage or Lodging rsystems Built after 31, 1996 Schorest in public health is an JTPH'S system) nound surface? YES is an surface waters? YES is an surface waters? YES is an surface waters? YES is a surface waters? YES is a surface waters
Protection Are Systems bu Shoreland or B Is the sustem setury? (a yes - Discharge of se - Sevege backep - Situation with th adversely impe safety? Is the system - Less than TUD system bottom - A scapage pit, c Is the system operating permit If yes, - Hep the requir (If no, the system	It prior to April 1, 1996 and re Wellhead Protection Area or S everage or Lodging Establishme answar is an ITPHS system) wage to the ground surface? wage to drainille or surface? wage to drainille or surface? wage to drainille or surface? and selfing? to potential to immediately and act or threaten public heads or <u>failEng? (a yes answer is a fail</u> feer of vertical separation between and selfand? (a yes answer is a fail feer of vertical separation between and selfand? (a yes answer is a fail feer of vertical separation between and selfand? (a yes answer is a fail feer of vertical separation between and selfand? (a yes answer is a fail feer of vertical separation between and selfand? (a yes answer is a fail feer of vertical separation between and selfand? magnification of a period of the selfand (a find, go to pege 2) ed monitoring taken place?	Not located in erving a Food, ant NES NO YES NO YES NO YES NO YES NO YES NO YES NO YES NO	Systems located in Shor Areas or Serving a Fo Establishment, or March Is the system an immine or satisfy? (a yes answer i - Lischarge of sevage to their - Savage backup into dwelling - Less then THREE feet of vert system bottom and savate - A seepage pit, caspool, dryw Te the system regulated operating permit? (if no, go i If yes, - Has the required monitorin	eland or Wellhead Protection od, Beverage or Lodging resistants Built after 31, 1996 Statistical in public health S an JTPH'S system) nound surface? YES 2 Y
Protection Are Systems bu Shoreland or B Is the system Selety? (2 yes Discharge of se Discharge of se Discharge of se Sewage backap Stoatlon with H adversely impe safety? Is the system System bottom - A seepage pit, c Is the system operating permit If yes, - Has the requin (If no, the system - Does the monit	It prior to April 1, 1996 and re Wellhead Protection Area or S everage or Lodging Establishme answar is an IIPH'S system) wage to the ground surface? wage to the ground surface? wage to the dround surface? and welling? the potential to Insuediately and act or threaten public heading of SelfErso? (a yes answer is a fail feet of vertical separation between and selurated soft or between and selurated under a monitoring place? in is non-complying)	Not located in erving a Food, ant NES NO YES NO YES NO YES NO YES NO YES NO YES NO YES NO	Systems located in Shor Areas or Serving a Fo Establishment, or March Is the system an initial or softwill (a yes answer is - Discharge of severe to drein - Severe of severe to drein - Severe bodop into dweling - Discharge of severe to drein - Severe for with the potential in adversely impact or threater safety? Is the system fertime? (a - Less then THESE feet of vert system bottom and saturate - A seepage pit, casspool, dryw Is the system regulated coerating permit? (if no, go i If yes, - Has the required monitorin (If no, the system is non-com	eland or Wellhead Protection od, Beverage or Lodging rsystems Built after 31, 1996 ELANCENT to public health S an JTPH'S system) nound surface? VES The or surface waters? VES 2 YES 2

wq-wwjsts4.31



coll Borings (BR #): Locate each boring on the map above, indicate on the right of the column the soft many structure, color, depth of each different soft type, evidence of monthing, bedrock and standing water. Also indicate if the material is fill



RECORD DEFTH OF MOTTLING, SEASONAL HIGH WATER (AS DELERMINED USING THE MINISELL COLOR BOOK) OR BEDROCK ON ABOVE LINES

in compliance and working under current use as -20-07

What needs to be completed to bring the above system into compliance if forest not in compliance?

winning _ ash trendstein morning fac

	TMENT SYSTEM INSPECTION FORM
	UNTY, MINNESOTA
Township <u>Haulton</u> Date	e of Inspection <u>5-7-01</u> Permit Number <u>27726</u>
Owner Les Moser	Parcel Number 11-1-090706
Project Address VIOI hox 254	Installer Dennir O'deill
City <u>AIHCIA</u> Zip Code 5	5 6431 New Repair
	DIST. or DROP BOX & TYPE
SETBACKS: Buildings to tank(s) 30 ¹	TRENCHES, BEDS, OR GRAVELLESS LEACHFIELD:
Buildings to drainfield 6014	Trench length
Well(s) 50' or 100' <u>NA</u>	Trench bottom width
Lake/Creek/Wetland <u>/ 58 '</u>	Trench bottom level
SEPTIC TANKS:	Trench spacing
Liquid capacity 1860 Combo	Drainfield rock below pipe
Manufacturer & type Jac Pre-Cast	
Type of baffle Mastric	Depth of backfill
Inspection pipes 9 - 4" 1-6"	Absorption area: square feet
Manholes access	(lineal feet
No. & height of risers 24 ¹¹	
MOUNDS:	PUMPS:
Percent slope	
Upslope dike width	
Downslope dike width	Ý
Sideslope dike width	Pump manufacturer & model#
Drainfield rock below pipe?	Horsepower & GPM
Depth of sand below rock $2' - 3'/_2$	Feet of head
Perforation size & spacing	Cycles per day
Perforation size & spacing Pipe size & spacing?	Gallons per cycle
Dimensions of rock bed <u>10 × 40</u>	Size of discharge line
Dimensions of sand base 46X 64	Type of electrical hookup
Final cover 50 × 70 14 th creater	Type & location of alarm POWLY 1255
DRAWING OF SYSTEM Won Korka	Les Cycle counter (commercial)
	10 5%
No Wall	
18 A March	43/11/1
E Course	1001
	Tank Hale +++ 11 ->>
	Soil III
	And you you have a second and a
	30' Q. O TO 15"
and the second se	L_1X00 1 3,01
	INN IN
4.77.01 -11.4. 1	470 1.
Inspector's Comments T-6701 -Scarification O (I Told Dannis To Comer 5	Ak - dy the fine sal low soil. Chinamp should 60.
(1010 pannis 10 Cover 1	Tank de He wants To) stofe-

Corrective Action Re	quired	*****			*****
Inspector's Signature	4.22	Film	Installer's Si	gnature	
X		White-County	Yellow-Applicant	Pink-Installer	

.....



Analysis Report

September 05, 2023

INVOICE TO:

Sandmann, Doug 43042 Conifer St Aitkin MN 56431

REPORT TO:

Date Rcvd-Brnd:	8/28/2023	Sampled By:	Steve - AWRL	LOCATION:
Time Rcvd-Brnd:	12:53	Sample Type:	DW	Sandmann, Doug
		Recv Temp°C:	15.3 on ice	43042 Conifer St
		TYPE:	Well Water	Aitkin MN 56431

SITE / TEST PERFORMED 	Sample Date/Time	Your Result	Units	Acceptable Level	Analytical Method	Analysis Date/Time	Analyst	Code #
Kitchen Tap	8/28/2023 @ 11:2	27						
Coliform, Total		ABSENT	/100mL	ABSENT	SM 9223 B (COLISURE)-2016	8/28/23 14:44	CJS	081210
Eschericha coli (E. coli)		ABSENT	/100mL	ABSENT	SM 9223 B (COLISURE)-2016	8/28/23 14:44	CJS	081210
Nitrate, as N		< 0.100	mg/L	< 10	EPA 353.2 REV 2.0	8/29/23 11:48	MH	081210

Sample 081210: This sample meets the State of Minnesota and EPA Guidelines for safe drinking water for the analytes tested.

Approved By:

SalaChley

Date Approved: 9/5/2023

Sara Ahlers, Laboratory Director

A.W. Research Laboratories, Inc. is accredited by the MNELAP and follows approved methods and procedures. MN State Laboratory ID: 027-035-135 and EPA Lab Code: MN00098. All data generated using non-accredited methods noted as -NC, and all analytes for which accreditation is unavailable -NA. The results above relate only to the samples tested. This report must not be reproduced, except in full, without the written approval of the laboratory. We appreciate your feedback, please email us at awlab@awlab.com with questions or comments. Thank you!

~End of Analysis Report~



CRV Filed No Delinquent Taxes and Transfer Entered Kirk Peysar, County Auditor State Deed Tax Paid Lori Grams, County Treasurer

Doc No: A479113

WAD 1/2

Certified Filed and/or Recorded on 10/16/2023 1:57 PM

 REC FEE
 \$46.00

 SDT
 \$1386.00

 eCRV #
 1590690

Office of the County Recorder Aitkin County, Minnesota Tara Snyder, County Recorder

Package: 84491 Terri

WARRANTY DEED Individual(s) to Individual(s) Minnesota Uniform Conveyancing Form 10.1.1 (2018)

Date: October 6, 2023 E-CRV No. /590690 DEED TAX DUE: \$1,386.00

FOR VALUABLE CONSIDERATION, Doug Sandmann aka Douglas Sandmann, a single person, ("Grantor"), hereby conveys and warrants to Roland Wapola and Carol Wapola, ("Grantee"), as

(Check only one box.)

☐ tenants in common,☑ joint tenants,

(if more than one Grantee is named above and either no box is checked or both boxes are checked, this conveyance is made to the named Grantees as tenants in common.)

real property in Aitkin County, Minnesota.

Complete legal description attached hereto as Exhibit A and by this reference incorporated herein.

Check here if all or part of the described real property is Registered (Torrens) □

together with all hereditaments and appurtenances belonging thereto, subject to the following exceptions:

Check box if applicable:

- □ The Seller certifies that the seller does not know of any wells on the described real property.
- □ A well disclosure certificate accompanies this document or has been electronically filed. (if electronically filed, Insert WDC number)
- I am familiar with the property described in this instrument and I certify that the status and number of wells on the described real property have not changed since the last previously filed well disclosure certificate.

U.S._Minnesota _Warranty Deed (Individual)

Elite Title & Escrow 13954 Cypress Drive, Suite 200 Baxter, MN 56425 10733-23 Page 1 of 3 Pages

manan

Doug Sandmann

Affix Deed Tax Stamp Here


} } ss.

}

STATE OF MINNESOTA

COUNTY OF CROW WING

This instrument was acknowledged before me on October 02, 2023, by Doug Sandmann aka Douglas Sandmann, a single person.



Tax Statements for the real property described in this instrument should be sent to (include name and address of Grantee):

THIS INSTRUMENT WAS DRAFTED BY (NAME AND ADDRESS):

First American Title Insurance Company 6900 Wedgwood Road North Suite 170 Maple Grove, MN 55311 1643155

Roland Wapola and Carol Wapola 48042 conifer street 107 Lachite Aithin, MA 56431 Horseshoe Bay, 78657

EXHIBIT 'A'

LOTS FOUR (4) AND FIVE (5), OF COOLGALE PARK, AITKIN COUNTY, MINNESOTA.

U.S._Minnesota _Warranty Deed (Individual)

Page 3 of 3 Pages



Vacation/Private Home Rental App. # App-2023-001354, UID # 209306 App. Status: Pending Review

> Meeting date: 1/22/24 Date complete: 12/17/23 60 day: 2/14/24

Contact Information

Aitkin County Planning & Zoning / Environmental Services 307 2nd Street NW, Room 219 Aitkin, MN 56431 Phone: 218-927-7342 Fax: 218-927-4372 Email: aitkinpz@co.aitkin.mn.us

If we have questions on the application who should we contact?	Name: Greg & Jessica Malban Phone: (763) 234 - 3335 Email Address: gregthun@gmail.com Mailing Address: 11177 Stillwater Lane Woodbury MN 55129
you the property owner?	Yes
Do you have a contact person that meets all requirements of Section 17.0 (17) of the Aitkin County	Yes
Zoning Ordinance?	

12/26/23, 12:29 PM

Project Location Search

	Property Location		Legal Description			Property Attributes		Owner Information	Tax Payer Information	
Property:	Parcel Number	Property Address	Township or City Name	Legal Description	Plat Name	Section- Township- Range	Lake Class	Lake Name	Owner Name(s)	Taxpayer Name(s)
	29-1- 516500	17854 476th Ln MCGREGOR, MN 55760	SHAMROCK TWP	LOT 9 BLK 1	PIERCE ADDITION	S:26 T:49 R:23	GD	MINNEWAWA LAKE	MALBAN, GREGORY & JESSICA	MALBAN, GREGORY & JESSICA
Driving directions to the property from Aitkin:	Left onto H Right onto Right onto Left onto 4 Right onto		• •	ities						

12/26/23, 12:29 PM

Brief Narrative

OneGov

Brief Narrative:	Our cabin will primarly be used for our personal vacations. We plan to provide the cabin as a rental on Airbnb occasionally. # of proposed occupants: 5 maximum Proposed length of stay: 2-7 days Proposed quiet hours: 10pm to 8 pm daily We will list our property on Airbnb and/or VRBO					
List all current advertising sources: (Be specific and include website links, rental ID #'s, title, etc.) All advertising must be in compliance with the occupancy allowance and all other conditions of the permit. Notify Environmental Services with any changes to the advertising within 30 days.	We don't have any advertising yet because our property is not licensed					
Proposed occupancy of overnight guests:	5					
How many rental units will be located on this parcel?	1					
Will you be renting for periods of less than one week?	Yes					
Quiet hours will begin at:	10 : 00 <u>PM</u>					
Quiet hours will end at:	08 : 00 <u>AM</u>					

12/26/23, 12:29 PM

Floor Plan of Structure

 Please attach a floor plan of the rental unit that includes the following: Label sleeping areas with dimensions Location of egress windows and doors Location of all smoke alarms and carbon monoxide alarms 	File 1: Cabin_License_Floor_Plan.jpg
2. How many rooms will be used for sleeping?	2
3. How many carbon monoxide alarms are located in the rental?	3
4. How many smoke detector alarms are located in the rental?	3
5. A fire extinguisher must be placed in an easily accessible location within each rental unit. Where is the fire extinguisher located?	One; mounted in garage next to kitchen


Sleeping Area #1

Was this window installed before July 10, 2007?	Yes
Select Window style. (see attached diagram for window style options):	Double Hung
What is the OPENABLE height of this window:	25.25 inches
What is the OPENABLE width of this window:	35 inches
What is the distance from the floor to the bottom of this window (finished sill):	24 inches

Sleeping Area #2

Was the largest window in this room installed before July 10, 2007?	Yes
Select window style. (see attached diagram for window style options):	Double Hung
What is the OPENABLE height of this window?	24.25 inches
What is the OPENABLE width of this window?	35 inches
What is the distance from the floor to the bottom of this window (finished sill)?	24 inches

Scaled Site Plan



Emergency Contact Info

Police:	(218) 927 - 7435
Fire:	(218) 768 - 2717
Hospital:	(218) 927 - 2121
Septic Tank Pumper:	(218) 927 - 6175
Where in the rental will the emergency contact information be posted?	2 Locations: kitchen and guidebook (living room)

Property Information Handbook

Please select all that will be included in your handbook:	Name & contact information for owner and/or caretaker Quiet hours Maximum # of overnight guests Maximum # of non-overnight guests Property rules related to outdoor features List of conditions placed on the approved IUP Notice that all ordinances and IUP conditions will be enforced by the Aitkin County Sheriff's Office and the Aitkin County Environmental Services Department
Where in the rental will your handbook will be located?	Kitchen Table

Septic Compliance

|--|

Water Test Results

Attach Water Test:	File 1: 🖶 202377_RBJOent.pdf	


Garbage Disposal Plan

How often will the garbage be collected?	Once per week
Please enter the name of the garbage collection service or describe your disposal plan:	Lakes Sanitary Svc.

Pet Policy

Pet Policy:	No pets allowed
-------------	-----------------

Property Deed



Additional Info

OneGov

Additional Info (optional): This cabin is primarily our family cabin and will only be rented out intermittently to small groups of 4 people maximum.

Terms

Interior & Exterior Inspection

After your submitted application is accepted by Environmental Services, a staff member will contact you to schedule an interior inspection to verify the information provided in your application. It is the responsibility of the applicant to have the following in place prior to the inspection:

1. Smoke alarms and carbon monoxide alarms installed per MN State Fire Code

2. Fire extinguishers are in their designated places and meeting MN State Fire Code

3. Flow-measuring device installed on the septic system or well

4. Visual demarcations of the property lines

Shamrock Township Lodging Tax Ordinance

If the proposed VRBO is located within Shamrock Township, please be aware there is a Lodging Tax Ordinance that will apply to this rental. For more information, please contact Shamrock Township at (218) 426-3736.

General Terms

The landowner or authorized agent hereby certifies that to the best of their knowledge the application and supporting documents are a factual representation of the proposed project. The landowner or authorized agent agrees that, in making application, the landowner grants permission to Aitkin County, at reasonable times, to enter the property to determine compliance of the application with applicable Local, County or State Ordinances or Statutes. It is the applicant's responsibility to contact other Local, County or State agencies to ensure the applicant has complied with all relevant Local, County or State Ordinances or Statutes.

Submittal of the above materials does not always constitute a complete application. Other information may be necessary to complete the application based on the type of request and onsite inspection.

I acknowledge that by submitting this application, the application and its attachments are public information.

OneGov

Invoice #58981 (12/17/2023) Expected Payment Method: Pay Online - Card or ECheck

Charge	Cost	Quantity	Total
Recording Fee added 11/03/2023 5:49 PM	\$46.00	x 1	\$46.00
This fee is non-refundable if denied.			
Vacation/Private Home Rental added 11/03/2023 5:49 PM	\$650.00	x 1	\$650.00
This fee is non-refundable if denied.			
Grand Total			
Total			\$696.00
Payment 12/17/2023			\$696.00
		Due	\$0.00

Approvals

Approval	Signature
Applicant	Jessica Malban - 12/17/2023 5:23 PM
	306138abbd35f5c2b68609b8deac82e4
	73c2cc22e749e4da302c1f7c67d17bf8
#1 Administrative Staff	Connor Plagge - 12/19/2023 4:15 PM
	522cda7e71c963fcc6658556080e1b10
	1bdfb1f06cf4d0a40701a265657f32b1
#2 Planning Commission	

Public Notes

Text:	To be heard at the January 22nd, 2024 Planning Commission meeting.	


OneGov


File(s):	

Administrative Staff

This review has been started by:	Connor Plagge V
Zoning District:	Shoreland V
Is the parcel a Lot of Record before 1-21-92 or have alternate sites been identified?	Yes 🗸
Is this an After-The-Fact application?	No 🗸
Current SSTS:	Pressure Bed/Seepage
Max Overnight Guests per SSTS:	5

Print View







Water Analysis Report Aitkin County Environmental Services Water Lab Wednesday, July 26, 2023

Report To: Beverly Rath 19595 484 St McGregor, MN 55760

Date Collected: 07/25/23 Time Collected: 11:40 AM

Collected by: Brock Anderson Source: Outdoor tap Temp Received: <46°F Sample Location: RBJO Enerprises 17854 476th Ln McGregor, MN 55760

Sample #: 202377

Test Performed	Your Results	Units	Acceptable Level	Analytical Method	Analyst	Analysis Date/ Time
Nitrate Nitrogen	< 1.00	mg/L	< 10	E004	BA	07/25/23 4:00PM
Coliform	Absent	_		SCC1	BA	07/25/23 3:30PM & 07/26/23 3:30PM
E. Coli	Absent	_		E009	BA	07/25/23 3:30PM & 07/26/23 3:30PM

Results approved by Andrew Carlstrom, Environmental Services Director

Samples received at temperatures above 46°F that were received more than 20 minutes after the sample was collected will have the nitrate-nitrogen results estimated. Bacteria and nitrate-nitrogen tested per SM 9223B 20th Ed. and SM 4500-NO3 D 20th Ed. This lab utilizes NELAC Standard 2003 practices. This report must not be reproduced except in full without written approval from this laboratory. These water test results are public information.

End of Water Analysis Report



520 Lafayette Road North St. Paul, MN 55155-4194

Compliance inspection report form

Existing Subsurface Sewage Treatment System (SSTS)

Doc Type: Compliance and Enforcement

Instructions: Inspector must submit completed form to Local Governmental Unit (LGU) and system owner within 15 days of final determination of compliance or noncompliance. Instructions for filling out this form are located on the Minnesota Pollution Control Agency (MPCA) website at https://www.pca.state.mn.us/sites/default/files/wq-wwists4-31a.pdf.

Property information	Local tracking	number:	
Parcel ID# or Sec/Twp/Range: 29-1-516500 Local regulatory authority info: <u>Aitkin county planning and zoning</u>	Reason for Inspection	Transfer of property.	
Property address: <u>17854 476th</u> . In.McGregor,Mn.55760 Owner/representative: <u>Paul Fisher</u> Brief system description: 1860 gallon combo tank that pumps up in		Owner's phone: ed.	

System stat	tu:	S
-------------	-----	---

System status on date (mm/dd/yyyy): _4/15/2022

☑ Compliant – Certificate of compliance*

(Valid for 3 years from report date unless evidence of an imminent threat to public health or safety requiring removal and abatement under section 145A.04, subdivision 8 is discovered or a shorter time frame exists in Local Ordinance.)

*Note: Compliance indicates conformance with Minn. R. 7080.1500 as of system status date above and does not guarantee future performance.

Noncompliant – Notice of noncompliance

Systems failing to protect ground water must be upgraded, replaced, or use discontinued within the time required by local ordinance.

An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance or under section 145A.04 subdivision 8.

Reason(s) for noncompliance (check all applicable)

□ Impact on public health (Compliance component #1) – Imminent threat to public health and safety

□ Tank integrity (Compliance component #2) – Failing to protect groundwater

Other Compliance Conditions (Compliance component #3) – Imminent threat to public health and safety

Other Compliance Conditions (Compliance component #3) – Failing to protect groundwater

System not abandoned according to Minn. R. 7080.2500 (Compliance component #3) – Failing to protect groundwater

Soil separation (Compliance component #5) – Failing to protect groundwater

Operating permit/monitoring plan requirements (Compliance component #4) – Noncompliant - local ordinance applies

Comments or recommendations

Certification

I hereby certify that all the necessary information has been gathered to determine the compliance status of this system. No determination of future system performance has been nor can be made due to unknown conditions during system construction, possible abuse of the system, inadequate maintenance, or future water usage.

By typing my name below, I certify the above statements to be true and correct, to the best of my knowledge, and that this information can be used for the purpose of processing this form. Cortification number: C-4744

		Certification number. o n n
Business name: Farley sewer systems		License number: L-1919
Inspector signature:	ically signed)	Phone: 218-839-4737
Necessary or locally required support	ing documentation (must be atta	iched)
Soil observation logs System/As-Built	Locally required forms Tank Integrity As	ssessment
Other information (list):		
cc1 205 5200 • 8	00-657-3864 • Use your preferred relay servic	e • Available in alternative formats

Page 1 of 4

Business Name: Farley sewer systems

1. Impact on public health – Compliance component #1 of 5

Compliance criteria:			Attached supporting documentation:
System discharges sewage to the ground surface	□ Yes*	🖾 No	Other: Not applicable
System discharges sewage to drain tile or surface waters.	□ Yes*	No No	
System causes sewage backup into dwelling or establishment.	☐ Yes*	No No	
Any "yes" answer above indicates imminent threat to public health an	the systend safety.	em is an	

Describe verification methods and results:

Tank integrity – Compliance component #2 of 5

Compliance criteria:		Attached supporting documentation:
System consists of a seepage pit,	🗆 Yes* 🖾 No	Empty tank(s) viewed by inspector
cesspool, drywell, leaching pit,		Name of maintenance business: Kangas Ent.
or other pit?	□ Yes* ⊠ No	License number of maintenance business: L-2526
Sewage tank(s) leak below their designed operating depth?		Date of maintenance: 4/15/2022
		Existing tank integrity assessment (Attach)
		Date of maintenance (mm/dd/yyyy): (must be within three years)
If yes, which sewage tank(s) leaks: Any "yes" answer above indicates the system		(See form instructions to ensure assessment complies with Minn. R. 7082.0700 subp. 4 B (1))
is failing to protect groundwate	57.	Tank is Noncompliant (pumping not necessary – explain below)
		Other:

Describe verification methods and results:

•

.

Property Address: _____17854 476th. In.McGregor,Mn.55760

Business Name: Farley sewer systems

3. Other compliance conditions – Compliance component #3 of 5

		10
	3a. Maintenance hole covers appear to be structurally unsound (damaged, cracked, etc.), or unsect □ Yes*	
	3b. Other issues (electrical hazards, etc.) to immediately and adversely impact public health or safety	? 🗌 Yes* 🛛 No 🗌 Unknown
	*Yes to 3a or 3b - System is an imminent threat to public health and safety.	
	3c. System is non-protective of ground water for other conditions as determined by inspector?	🗌 Yes* 🛛 No
	3d. System not abandoned in accordance with Minn. R. 7080.2500?	🗌 Yes* 🛛 No
	*Yes to 3c or 3d - System is failing to protect groundwater.	
	Describe verification methods and results:	
	Describe vernication includes and recaining	
	Attached supporting documentation: Not applicable	
4.	 Operating permit and nitrogen BMP* – Compliance component #4 o 	f 5 🛛 Not applicable
		f "yes", A below is required
	Is the system operated under an Operating Permit?	f "yes", B below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? ∐ Yes ∐ No	f "yes", B below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? \Box Yes \Box No BMP = Best Management Practice(s) specified in the system design	f "yes", B below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? ∐ Yes ∐ No	f "yes", B below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria:	f "yes", B below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? ☐ Yes ☐ No	f "yes", B below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? ☐ Yes ☐ No b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No	f "yes", B below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? ☐ Yes ☐ No b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No	f "yes", B below is required
	 Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? D Yes ☐ No b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No Any "no" answer indicates noncompliance. 	f "yes", B below is required
	Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? ☐ Yes ☐ No b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No	f "yes", B below is required
	 Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? D Yes ☐ No b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No Any "no" answer indicates noncompliance. 	f "yes", B below is required
	 Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? D Yes ☐ No b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No Any "no" answer indicates noncompliance. 	f "yes", B below is required
	 Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? D Yes ☐ No b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No Any "no" answer indicates noncompliance. 	f "yes", B below is required
	 Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? D Yes ☐ No b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No Any "no" answer indicates noncompliance. 	f "yes", B below is required
	 Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? D Yes ☐ No b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No Any "no" answer indicates noncompliance. 	f "yes", B below is required
	 Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? D Yes ☐ No b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No Any "no" answer indicates noncompliance. 	f "yes", B below is required
	 Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? D Yes ☐ No b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No Any "no" answer indicates noncompliance. 	f "yes", B below is required
	 Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? D Yes ☐ No b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No Any "no" answer indicates noncompliance. 	f "yes", B below is required
	 Is the system required to employ a Nitrogen BMP specified in the system design? ☐ Yes ☐ No BMP = Best Management Practice(s) specified in the system design If the answer to both questions is "no", this section does not need to be completed Compliance criteria: a. Have the operating permit requirements been met? D Yes ☐ No b. Is the required nitrogen BMP in place and properly functioning? ☐ Yes ☐ No Any "no" answer indicates noncompliance. 	f "yes", B below is required

Property Address: ____17854 476th. In.McGregor,Mn.55760

Business Name: Farley sewer systems


5. Soil separation – Compliance component #5 of 5

•••••			
Date of installation10/17/2005 (mm/dd/yyyy)	🗌 Unknown		
 Shoreland/Wellhead protection/Food beverage lodging? Compliance criteria (select one): 5a. For systems built prior to April 1, 1996, and not located in Shoreland or Wellhead Protection Area or not serving a food, beverage or lodging establishment: Drainfield has at least a two-foot vertical separation distance from periodically saturated soil or bedrock. 	Yes No	 Attached supporting documentation: Soil observation logs completed for the □ Two previous verifications of required □ Not applicable (No soil treatment area Soil boring info:Soil info is on the map 	vertical separation)
 saturated soil of bedrock. 5b. Non-performance systems built April 1, 1996, or later or for non- performance systems located in Shoreland or Wellhead Protection Areas or serving a food, beverage, or lodging establishment: Drainfield has a three-foot vertical separation distance from periodically saturated soil or bedrock.* 	⊠ Yes □ No*	Indicate depths or elevationsA. Bottom of distribution mediaB. Periodically saturated soil/bedrockC. System separationD. Required compliance separation**May be reduced up to 15 percent if all Ordinance.	98 95 36" 36" owed by Local
5c. "Experimental", "Other", or "Performance" systems built under pre-2008 Rules; Type IV or V systems built under 2008 Rules 7080. 2350 or 7080.2400 (Intermediate Inspector License required ≤ 2,500 gallons per day; Advanced Inspector License required > 2,500 gallons per day) Drainfield meets the designed vertical separation distance from periodically saturated soil or bedrock.	☐ Yes ☐ No*		

*Any "no" answer above indicates the system is failing to protect groundwater.

Describe verification methods and results:

Upgrade requirements: (Minn. Stat. § 115.55) An imminent threat to public health and safety (ITPHS) must be upgraded, replaced, or its use discontinued within ten months of receipt of this notice or within a shorter period if required by local ordinance. If the system is failing to protect ground water, the system must be upgraded, replaced, or its use discontinued within the time required by local ordinance. If an existing system is not failing as defined in law, and has at least two feet of design soil separation, then the system need not be upgraded, replaced, or its use discontinued, notwithstanding any local ordinance that is more strict. This provision does not apply to systems in shoreland areas, Wellhead Protection Areas, or those used in connection with food, beverage, and lodging establishments as defined in law.



(Top 3 inches reserved for recording data
ANTAL ANALASSA

WARRANTY DEED Individual(s) to Joint Tenants

Minnesota Uniform Conveyancing Blanks Form 10.1.5 (2013)

e-CRV No.: N/A Consideration less than \$3000

DEED TAX DUE: \$1.65


DATE: November 3, 2023

FOR VALUABLE CONSIDERATION, Gregory Malban and Jessica Malban, spouses married to each other ("Grantor"), hereby conveys and warrants to Gregory Malban and Jessica Malban, ("Grantee"), as joint tenants, real property in Aitkin County, Minnesota, legally described as follows:

Legal description attached hereto and made a part hereof marked Exhibit "A"

Check here if all or part of the described real property is Registered (Torrens)

together with all hereditaments and appurtenances belonging thereto, subject to the following exceptions:



Page 2 of 3


Minnesota Uniform Conveyancing Blanks Form 10.1.5

Check applicable box:

- The Seller certifies that the Seller does not know of any wells on the described real property.
- A well disclosure certificate accompanies this document or has been electronically filed. (If electronically filed, insert WDC number:
- I am familiar with the property described in this instrument and I certify that the status and number of wells on the described real property have not changed since the last previously filed well disclosure certificate.

State of Minnesota, County of Washington

This instrument was acknowledged before me on November 3rd, 2023, by Gregory Malbamand Jessica Malban, spouses married to each other.



(signature of notarial officer Title (and Rank): anader My commission expires: JCIN 51 (month/day/year)

THIS INSTRUMENT WAS DRAFTED BY: Lawyers Title Services, LLC 7153 Forthun Road, Suite 110 Baxter, MN 56425

TAX STATEMENTS FOR THE REAL PROPERTY DESCRIBED IN THIS INSTRUMENT SHOULD BE SENT TO: Gregory and Jessica Malban 11177 Stillwater Lane Woodbury, MN 55129

Grantor Gregory Malban

Jessica Malban



EXHIBIT "A"

Lot Nine (9), Block One (1), Pierce Addition, according to the filed plat thereof.

Aitkin County, Minnesota.

Abstract Property